

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIS23001500/RYA3Q2**Date:** 06/07/2023REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SLE8684E**Insured Vehicle No :** YP6527C

Date of Loss: 10/02/2023

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLE8684E**

Make &amp; Model: VOLKSWAGEN ARTEON, 2.0 R-LINE (A)

Engine No: DNN106163

Reg. Date: 25/10/2022 (Man. Year: 2022)

Chassis No: WVVZZZ3HZPE001072

Colour: Black

Odometer: 3450 km

Engine Capacity: 1984 cc

Market Value/New Car Price: N/A

Price:

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/35 R20

Rear Tyre Size: 245/35 R20

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                                       | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|---|-------------------|-------------------|-------------------|---------------|
| Parts   | 2,766.61          | 1,853.47          | 913.14            | 33.01         |
| Miscellaneous Items   | 0.00              | 0.00              | 0.00              |               |
| Labour  | 4,960.00          | 2,860.00          | 2,100.00          | 42.34         |
| Paintwork Labour  | 0.00              | 0.00              | 0.00              |               |
| Towing  | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>                                    | <b>7,726.61</b>   | <b>4,713.47</b>   | <b>3,013.14</b>   | <b>39.00</b>  |
| <b>+ GST 8.00/8.00% (S\$)</b>                               | 618.13            | 377.08            | 241.05            | 39.00         |
| <b>Nett Amount (S\$)</b>                                    | <b>8,344.74</b>   | <b>5,090.55</b>   | <b>3,254.19</b>   | <b>39.00</b>  |
| <b>+ Car Rental (3.0 x S\$111.12/day + 8.00% GST) (S\$)</b> |                   | 360.03            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                               |                   | 2.00              |                   |               |
| <b>Nett Liability (S\$)</b>                                 |                   | <b>5,452.58</b>   |                   |               |

INSPECTION

Date of Assignment: 11/02/2023

Date Inspected: 14/02/2023 Inspected At:

Volkswagen Group Singapore Pte Ltd  
247 ALEXANDRA ROAD  
Singapore 159934

Estimated Period of Repair: 3.0 days

**Adjuster:** MOHD RASUL**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

|               |  |  |
|---------------|--|--|
| Reference     |  |  |
| Part Source:  | MRM-SG   | Version: 1.0 (Last Synchronised: 06 Jul 2023)                      |
| Parts:        | 143  | VOLKSWAGEN ARTEON 2.0 R-LINE (A) (Catalogue:Merimen Singapore 1.0) |
| Labour:       | Repairer's   | (Price-denominated Standard List)                                  |
| Print Code:   | (Unsubmitted, no print-code for SLE8684E)  |  |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |  |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.   |  |

Recommended Parts

| No.                          | Qty | Part No. | Particulars                | Condition     | Repairer's  | Amount       |
|------------------------------|-----|----------|----------------------------|---------------|-------------|--------------|
| 1                            | 1   |          | *REAR VIEW MIRROR HOUSING  | Cracked       | 1,615.32 FS | *1,615.32 FS |
| 2                            | 1   |          | *MIRROR GLASS              | Not Necessary | 710.81 FS   | *- FS        |
| 3                            | 1   |          | *MIRROR CAP PRIMED         | Cracked       | 160.10 FS   | *160.10 FS   |
| 4                            | 1   |          | *WARNING DISPLAY FOR LANE  | Not Necessary | 124.28 FS   | *- FS        |
| 5                            | 1   |          | *EMBLEM AT RHF FENDER SIDE | Necessary     | 78.05 FS    | *78.05 FS    |
| 6                            | 1   |          | *EMBLEM AT RHF DOOR SIDE   | Not Necessary | 78.05 FS    | *- FS        |
| F=Franchise part. S=SpcNett. |     |          |                            |               |             |              |
| Total Parts (\$\$)           |     |          |                            |               | 2,766.61    | 1,853.47     |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                             | Lab.Type | Repairer's      | Amount          |
|---------------------------------|---|----------|-----------------|-----------------|
| <b>Labour Items</b>             |   |          |                 |                 |
| 1                               | B&P CHECK SHORT CIRCUIT /HARNESS REPAIR | New      | 280.00          | 280.00          |
| 2                               | B&P DIAGNOSIS AND PROGRAMMING           | New      | 480.00          | 480.00          |
| 3                               | LABOUR                                  | New      | 2,160.00        | 1,080.00        |
| 4                               | SPRAY PAINTING                          | New      | 2,040.00        | 1,020.00        |
| <b>Gross Labour Cost (\$\$)</b> |   |          | <b>4,960.00</b> | <b>2,860.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >