

ASS. REC. BY:

REF:

AIG / 23001502/kp

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

1-B.1%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SNH 3917C Yr Regn: 10122

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BYD

e6

C.C.

Colour

M. Black

A/C: Insured / Std / NI / NA

Sp. Reading

27241

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

LCOC84DCXNO267119

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / ATRlm or

Tyre Size:

F:

215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Chao Yang

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

P 12/23

D.O.I.

14/2/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S Area

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS. SI

Parking

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Date: 10/02/2023

Vehicle No: SNH3917C

Model: BYD E6

Chassis: LC0CE4DCXN0267119

Reg. Year: 2022

Third Party Insurer: AIG

Third Party Veh No: SMU6003M

Date of Accident: 08/02/2023

Estimator: VICTOR

Surveyor:

Not Notion
Runway B4paim
4 day
11Pm @ 2800h

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR DOOR LH	1		<i>B</i> \$2,950.00 ✓
2	REAR DOOR HINGE	2	\$170.00	<i>N</i> \$340.00 X
3	REAR DOOR WEATHERSTRIP	1		<i>P</i> \$260.00 X
4	REAR FENDER LH	1		REPAIR
SUB TOTAL				\$3,550.00
LESS 10%				-\$355.00
PARTS TOTAL				\$3,195.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
S/N TOTAL				\$0.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST RR ACCIDENT AREA.

400
\$500.00

LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREA.

400
\$500.00

LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM.

60
\$120.00

TO TUFF KOTE & UNDERSEAL MATERIALS.

300
\$120.00

LABOUR TOTAL \$1,240.00

TOTAL \$4,435.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143

Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500

Tel: (+65) 6484 9919 Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047

Tel: (+65) 6481 1522 Fax: (+65) 6481 1011

