

Date: 10/02/2023

Vehicle No: SNH3917C

Model: BYD E6

Chassis: LC0CE4DCXN0267119

Reg.Year: 2022

Third Party Insurer: AIG

Third Party Veh No: SMU6003M

Date of Accident: 08/02/2023

Estimator: VICTOR

Surveyor:

*Not Withheld
Autonomy B4 gain
4 day*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR DOOR LH	1		<i>R</i> \$2,950.00 ✓
2	REAR DOOR HINGE	2	\$170.00	<i>R</i> \$340.00 X
3	REAR DOOR WEATHERSTRIP	1		<i>R</i> \$260.00 X
4	REAR FENDER LH	1		REPAIR
SUB TOTAL				\$3,550.00
LESS 10%				-\$355.00
PARTS TOTAL				\$3,195.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
S/N TOTAL				\$0.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST RR ACCIDENT AREA.

400
\$500.00

LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREA.

400
\$500.00

LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM.

\$120.00 *60*

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$120.00 *30*

LABOUR TOTAL \$1,240.00

TOTAL \$4,435.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: