

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120**Our File No:** CC3/AIG23001504/RVP3E2**Date:** 31/05/2023**REFERENCE**

Insured/Claimant:	DARA ROK ING	Policy No:	2070006889-02		
Date of Loss:	08/02/2023	Nature of Claim:	OD	Claim No:	7641460693SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMR8970Z</b>		
Make & Model:	AUDI A5, 2.0 SPORTBACK TFSI S TRONIC (A)	Engine No:	CVK087014
Reg. Date:	30/01/2020 (Man. Year: 2019)	Chassis No:	WAUZZZF59KA073043
Colour:	Grey	Odometer:	47171 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$165,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	32,915.00	20,015.52	12,899.48	39.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	29,152.00	12,187.00	16,965.00	58.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>62,067.00</b>	<b>32,202.52</b>	<b>29,864.48</b>	<b>48.12</b>
<b>- Excess (S\$)</b>	600.00	600.00	0.00	0.00
<b>(S\$)</b>	61,467.00	31,602.52	29,864.48	48.59
<b>+ GST 8.00/8.00% (S\$)</b>	4,917.36	2,528.20	2,389.16	48.59
<b>Nett Amount (S\$)</b>	<b>66,384.36</b>	<b>34,130.72</b>	<b>32,253.64</b>	<b>48.59</b>

**INSPECTION**

Date of Assignment:	13/02/2023		
Date Inspected:	10/02/2023	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	13.0 days		

**Adjuster:** MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	3,187.00 FS	*2,549.60 FS
2	1		*REAR BUMPER FIXING PARTS	Necessary	289.00 FS	*145.60 FS
3	1		*REAR BUMPER CHROME TRIM	Cracked	1,206.00 FS	*964.80 FS
4	1		*REAR BUMPER SECURING STRIP	Necessary	264.00 FS	*210.80 FS
5	1		*REAR BUMPER REFLECTOR - LH / RH	N/SNotNecessary/O/SScratched	98.00 FS	*38.72 FS
6	1		*REAR PARKING AID SENSOR - INNER / OUTER (2PCS)	Scratched (1Pc Only)	543.00 FS	*212.00 FS
7	4		*REAR PARKING AID SEAL RING	Necessary	11.00 FS	*8.32 FS
8	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	1,197.00 FS	*- FS
9	2		*REAR BUMPER IMPACT BAR GASKET - LH / RH	Not Necessary	34.00 FS	*- FS
10	1		*REAR BUMPER GUIDE SECTION - LH	Necessary	52.00 FS	*41.44 FS
11	1		*REAR BUMPER GUIDE SECTION - LH / RH	N/SNotNecessary/O/SCracked	54.00 FS	*21.36 FS
12	1		*REAR BOOT LID OPENING CONTROL UNIT	Not Necessary	528.00 FS	*- FS
13	1		*REAR TAILGATE OPENING SENSOR LINE	Not Necessary	230.00 FS	*- FS
14	1		*REAR CONTROL UNIT RETAINER	Not Necessary	10.00 FS	*- FS
15	1		*REAR AERIAL RETAINER	Not Necessary	30.00 FS	*- FS
16	1		*REAR TELEPHONE AERIAL	Not Necessary	197.00 FS	*- FS
17	2		*REAR AERIAL FEMALE CONNECTOR REMOVABLE HOUSING - LH / RH	Not Necessary	46.00 FS	*- FS
18	1		*REAR AERIAL WIRE ADAPTER	Not Necessary	392.00 FS	*- FS
19	1		*REAR AERIAL WIRE ADAPTER	Not Necessary	392.00 FS	*- FS
20	1		*REAR AERIAL FEMALE CONNECTOR REMOVABLE HOUSING	Not Necessary	23.00 FS	*- FS
21	1		*REAR AERIAL FEMALE CONNECTOR REMOVABLE HOUSING	Not Necessary	24.00 FS	*- FS
22	1		*SET REAR BUMPER WIRING	Not Necessary	751.00 FS	*- FS
23	1		*REAR LID	Bent	4,342.00 FS	*3,473.60 FS
24	1		*AUDI EMBLEM	Necessary	172.00 FS	*137.60 FS
25	1		*A5 INSCRIPTION	Necessary	110.00 FS	*87.60 FS
26	1		*REAR LID ATTACHMENT PARTS	Not Necessary	169.00 FS	*- FS
27	2		*REAR LID STOP BUFFER - LH / RH	Not Necessary	45.00 FS	*- FS
28	2		*REAR LID HINGE - LH / RH	Not Necessary	542.00 FS	*- FS
29	1		*REAR LID FLAP GASKET	Not Necessary	278.00 FS	*- FS
30	1		*REAR LID STRIKER PLATE	Not Necessary	86.00 FS	*- FS
31	1		*PACKING ADHESIVE	Necessary	22.00 FS	*16.88 FS
32	1		*REAR WINDOW NOT PRETREATED	Necessary	1,379.00 FS	*1,103.20 FS
33	1		*WINDOW PRIMER	Necessary	24.00 FS	*18.80 FS
34	1		*REAR ADDITIONAL BRAKE LIGHT	Necessary	680.00 FS	*543.60 FS
35	1		*REAR LID TRIM PANEL	Not Necessary	565.00 FS	*- FS
36	1		*REAR OUTER TAIL LIGHT - LH	Cracked	1,344.00 FS	*1,075.20 FS
37	1		*REAR OUTER TAIL LIGHT TRIM - LH	Scratched	36.00 FS	*28.08 FS
38	1		*REAR INNER TAIL LIGHT - LH	Cracked	1,200.00 FS	*960.00 FS
39	1		*REAR INNER TAIL LIGHT TRIM - LH	Missing	36.00 FS	*28.08 FS
40	1		*REAR LID STOP BUFFER	Not Necessary	23.00 FS	*- FS
41	1		*REAR SIDE PANEL - LH	Buckled	4,315.00 FS	*3,452.00 FS
42	2		*REAR VENT TRIM - LH / RH	Not Necessary	153.00 FS	*- FS
43	1		*REAR SIDE PANEL CONNECTING PLATE - LH	Not Necessary	78.00 FS	*- FS
44	1		*REAR SIDE PANEL REINFORCEMENT - LH	Not Necessary	243.00 FS	*- FS
45	1		*REAR D-PILLAR REINFORCEMENT - LH	Not Necessary	323.00 FS	*- FS
46	1		*REAR BOTTOM PLATE - LH OUTER	Not Necessary	535.00 FS	*- FS
47	1		*REAR WHEEL HOUSING LINER - LH	Torn	322.00 FS	*257.60 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
48	1		<b>*REAR WHEEL HOUSING LINER ATTACHMENT PARTS</b>	Necessary	187.00 FS	*149.20 FS
49	1		<b>*REAR SILENCER HEAT SHIELD - LH</b>	Not Necessary	179.00 FS	*- FS
50	1		<b>*REAR CENTRE SILENCER</b>	Bent	1,327.00 FS	*1,061.60 FS
51	1		<b>*REAR SILENCER - LH</b>	Bent	1,318.00 FS	*1,054.40 FS
52	2		<b>*REAR SILENCER DUAL CLIP</b>	Necessary	121.00 FS	*96.64 FS
53	1		<b>*EXHAUST SILENCER BRACKET</b>	Necessary	48.00 FS	*38.00 FS
54	1		<b>*REAR WINDSCREEN SEALANT</b>	Necessary	200.00 FS	*200.00 FS
55	1		<b>*1/4 GLASS SEALANT</b>	Necessary	100.00 FS	*100.00 FS
56	1		<b>*METAL FILLER POWDER</b>	Necessary	280.00 FS	*280.00 FS
57	1		<b>*ACRYLIC SEALANT</b>	Necessary	180.00 FS	*180.00 FS
58	1		<b>*CAVITY WAX</b>	Necessary	140.00 FS	*140.00 FS
59	1		<b>*STONE CHIP</b>	Necessary	180.00 FS	*180.00 FS
60	1		<b>*REAR NUMBER PLATE WITH HOLDER</b>	Not Necessary	80.00 FS	*- FS
61	1		<b>*SUNDRIES</b>	Necessary	600.00 FS	*45.60 FS
62	1		<b>*REAR 1/4 GLASS - LH</b> (Supplementary)	Necessary	844.00 FS	*675.20 FS
63	1		<b>*PRIMER</b> (Supplementary)	Necessary	24.00 FS	*18.80 FS
64	1		<b>*SILL PANEL TRIM ATTACHMENT PARTS - LH</b> (Supplementary)	Necessary	144.00 FS	*115.20 FS
65	1		<b>*SILL PANEL TRIM ADHESIVE TAPES</b> (Supplementary)	Necessary	230.00 FS	*183.60 FS
66	1		<b>*REAR EXHAUST CHROME TRIP</b> (Supplementary)	Bent	153.00 FS	*122.40 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$) 32,915.00 20,015.52**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CARRY OUT FIRST MEASUREMENT ON CAR-O-LINER	New	800.00	0.00
2	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR ASSY. INSPECT FOR FUNCTION AND RENEW ACCORDINGLY	New	360.00	360.00
3	TO RENEW LHS 1/4 GLASS AND REAR WINDSCREEN TO FACILITATE FENDER RENEWAL	New	600.00	600.00
4	TO INSTALL SOLAR FILM ON AFFECTED GLASS	New	400.00	400.00
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN AND 1/4 GLASS	New	200.00	150.00
6	TO REMOVE AND REINSTALL REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	280.00	280.00
7	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	New	1,600.00	1,600.00
8	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, SEAT BELTS, DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,600.00	1,600.00
9	TO REMOVE AND REINSTALL REAR EXHAUST SILENCER. RENEW ACCORDING TO DAMAGE AND ALIGN TO POSITION	New	480.00	480.00
10	TO REMOVE AND REINSTALL REAR SUSPENSION ASSEMBLY FOR CA-O-LINER REPAIRS	New	3,200.00	0.00
11	TO SETUP AND PLACE VEHICLE ON CAR-O-LINER	New	2,400.00	0.00
12	TO DISMANTLE REAR BUMPER AND REAR LID. RE-ALIGN BOTH REAR CHASSIS FRAMES TO SPECIFICATION OF ORIGIN. CUT OUT AND WELD LHS REAR FENDER AND INNER REINFORCEMENT PLATES. RENEW REAR BUMPER AND REAR LID. REINSTALL ALL PARTS REMOVED	New	11,200.00	3,500.00
13	TO RESPRAY REAR BUMPER, REAR LID, HINGES, LHS REAR FENDER, DOOR ENTRANCE, DRAIN PANEL, END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	5,600.00	3,025.00
14	TO CARRY OUT WHEEL ALIGNMENT	New	240.00	0.00
15	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			<b>Gross Labour Cost (\$)</b>	<b>29,152.00</b>
				<b>12,187.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >