

 **PREMIUM AUTOMOBILES**

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0164/2023/EQ  
**DATE** : 9-Feb-23  
**WIP** : 62483

**VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/2/2023**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
Attn: Motor Claims Dept  
Tel: **6880 4602** - Fax: **6880 4838**


**OWNER'S NAME** : MR DARA ROK ING  
**ADDRESS** : BLK 440 CHOA CHU KANG AVENUE 4  
#06-457  
SINGAPORE 680440  
**TELEPHONE** : HP +65 87155938  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 2070006889-02  
**VEHICLE NO** : **SMR 8970 Z**  
**MODEL CODE** : AUDI A5 SPORTBACK 2.0 TFS  
**MODEL YEAR** : 30/1/2020  
**ENGINE NO** : CVK 087014  
**CHASSIS NO** : WAUZZZF59KA73043  
**MILEAGE** : 47,171  
**DATE IN** : 8-Feb-23  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 8-Feb-23  
**PLACE OF ACCIDENT** : INTERSECTION AT TAMPINES ROAD AND TAMPINES  
INDUSTRIAL DRIVE



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 8970 Z**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO CARRY OUT FIRST MEASUREMENT ON CAR-O-LINER.	S/N \$ 800.00	?
2	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR ASSY. INSPECT FOR FUNCTION AND RENEW ACCORDINGLY.	S/N \$ 360.00	/
3	TO RENEW LHS 1/4 GLASS AND REAR WINDSCREEN TO FACILLITATE FENDER RENEWAL.	S/N \$ 600.00	/
4	TO INSTALL SOLAR FILM ON AFFECTED GLASS.	S/N \$ 400.00	/
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN AND 1/4 GLASS.	S/N \$ <del>200.00</del>	150
6	TO REMOVE AND REINSTALL REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$ 280.00	/
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 2,640.00</b>	



55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 8970 Z**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$	1,600.00 /	
8	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, SEAT BELTS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,600.00 /	
9	TO REMOVE AND REINSTALL REAR EXHAUST SILENCER. RENEW ACCORDING TO DAMAGE AND ALIGN TO POSITION.	S/N \$	480.00 /	
10	TO REMOVE AND REINSTALL REAR SUSPENSION ASSEMBLY FOR CAR-O-LINER REPAIRS.	S/N \$	3,200.00 ?	
11	TO SETUP AND PLACE VEHICLE ON CAR-O-LINER.	S/N \$	2,400.00 ?	
12	TO DISMANTLE REAR BUMPER AND REAR LID. RE-ALIGN BOTH REAR CHASSIS FRAMES TO SPECIFICATION OF ORIGIN. CUT OUT AND WELD LHS REAR FENDER AND INNER REINFORCEMENT PLATES. RENEW REAR BUMPER AND REAR LID. REINSTALL ALL PARTS REMOVED.	@500 X 7 \$	11,200.00 / 3500	
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 20,480.00</b>	



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 8970 Z**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
13	TO RESPRAY REAR BUMPER, REAR LID, HINGES, LHS REAR FENDER, DOOR ENTRANCE, DRAIN PANEL, END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	@550x5.5 \$ 5,600.00	3025
14	TO CARRY OUT WHEEL ALIGNEMENT.	S/N \$ 240.00	?
15	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 29,152.00</b>	



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 8970 Z

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	REAR BUMPER <i>torn /</i>	1	\$	3,187.00
2	REAR BUMPER FIXING PARTS <i>m /</i>	1	\$	289.00
3	REAR BUMPER CHROME TRIM <i>com /</i>	1	\$	1,206.00
4	REAR BUMPER SECURING STRIP <i>neu /</i>	1	\$	264.00
5	REAR BUMPER REFLECTOR - (LH) RH <i>1 pc sum</i>	2	\$	98.00
6	REAR PARKING AID SENSOR - INNER / OUTER <i>sum /</i>	1 /	\$	543.00
7	REAR PARKING AID SEAL RING <i>m /</i>	4	\$	11.00
8	REAR BUMPER REINFORCEMENT BEAM <i>?</i>	1	\$	1,197.00
9	REAR BUMPER IMPACT BAR GASKET - LH / RH <i>?</i>	2	\$	34.00
10	REAR BUMPER GUIDE SECTION - LH <i>?</i>	1	\$	52.00
11	REAR BUMPER GUIDE SECTION (LH) RH <i>com /</i>	2	\$	54.00
12	REAR BOOT LID OPENING CONTROL UNIT <i>?</i>	1	\$	528.00
13	REAR TAILGATE OPENING SENSOR LINE <i>?</i>	1	\$	230.00
14	REAR CONTROL UNIT RETAINER <i>?</i>	1	\$	10.00
15	REAR AERIAL RETAINER <i>?</i>	1	\$	30.00
16	REAR TELEPHONE AERIAL <i>?</i>	1	\$	197.00
17	REAR AERIAL FEMALE CONNECTOR REMOVABLE HOUSING - LH / RH <i>?</i>	2	\$	46.00
18	REAR AERIAL WIRE ADAPTER <i>?</i>	1	\$	392.00
19	REAR AERIAL WIRE ADAPTER <i>?</i>	1	\$	392.00
20	REAR AERIAL FEMALE CONNECTOR REMOVABLE HOUSING <i>?</i>	1	\$	23.00
<b>SUB TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$</b>	<b>8,783.00</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT



55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 8970 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR AERIAL FEMALE CONNECTOR REMOVABLE HOUSING ?	1	\$ 24.00	
22	REAR BUMPER WIRING SET ?	1	\$ 751.00	
23	REAR LID <i>st/</i>	1	\$ 4,342.00	
24	AUDI EMBLEM <i>m/</i>	1	\$ 172.00	
25	"A5" INSCRIPTION <i>m/</i>	1	\$ 110.00	
26	REAR LID ATTACHMENT PARTS ?	1	\$ 169.00	
27	REAR LID STOP BUFFER - LH / RH ?	2	\$ 45.00	
28	REAR LID HINGE - LH / RH ?	2	\$ 542.00	
29	REAR LID FLAP GASKET <i>X</i>	1	\$ 278.00	
30	REAR LID STRIKER PLATE <i>X</i>	1	\$ 86.00	
31	PACKING ADHESIVE <i>m/</i>	1	\$ 22.00	
32	REAR WINDOW NOT PRETREATED <i>rel/</i>	1	\$ 1,379.00	
33	WINDOW PRIMER <i>m/</i>	1	\$ 24.00	
34	REAR ADDITIONAL BRAKE LIGHT <i>rel/</i>	1	\$ 680.00	
35	REAR LID TRIM PANEL <i>X</i>	1	\$ 565.00	
36	REAR OUTER TAIL LIGHT - LH <i>cal/</i>	1	\$ 1,344.00	
37	REAR OUTER TAIL LIGHT TRIM - LH <i>sur/</i>	1	\$ 36.00	
38	REAR INNER TAIL LIGHT - LH <i>cal/</i>	1	\$ 1,200.00	
39	REAR INNER TAIL LIGHT TRIM - LH <i>ris/</i>	1	\$ 36.00	
40	REAR LID STOP BUFFER	1	\$ 23.00	
<b>SUB TOTAL SPARE PARTS</b>			<b>\$ 11,828.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	REAR SIDE PANEL - LH <i>hmr</i>	1	\$ 4,315.00	
42	REAR VENT TRIM - LH / RH ?	2	\$ 153.00	
43	REAR SIDE PANEL CONNECTING PLATE - LH ?	1	\$ 78.00	
44	REAR SIDE PANEL REINFORCEMENT - LH ?	1	\$ 243.00	
45	REAR D-PILLAR REINFORCEMENT - LH ?	1	\$ 323.00	
46	REAR BOTTOM PLATE - LH OUTER ?	1	\$ 535.00	
47	REAR WHEEL HOUSING LINER - LH <i>form</i>	1	\$ 322.00	
48	REAR WHEEL HOUSING LINER ATTACHMENT PARTS <i>m</i>	1	\$ 187.00	
49	REAR SILENCER HEAT SHIELD - LH ?	1	\$ 179.00	
50	REAR CENTRE SILENCER <i>cut?</i>	1	\$ 1,327.00	
51	REAR SILENCER - LH <i>st</i>	1	\$ 1,318.00	
52	REAR SILENCER DUAL CLIP <i>m</i>	2	\$ 121.00	
53	EXHAUST SILENCER BRACKET <i>m</i>	1	\$ 48.00	
54	REAR WINDSCREEN SEALANT <i>m</i>	S/N	\$ 200.00	
55	1/4 GLASS SEALANT <i>m</i>	S/N	\$ 100.00	
56	METAL FILLER POWDER <i>m</i>	S/N	\$ 280.00	
57	ACRYLIC SEALANT <i>m</i>	S/N	\$ 180.00	
58	CAVITY WAX <i>m</i>	S/N	\$ 140.00	
59	STONE CHIP <i>m</i>	S/N	\$ 180.00	
60	REAR NUMBER PLATE WITH HOLDER <i>X</i>	S/N	\$ 80.00	
61	SUNDRIES ?		\$ 600.00	
<b>TOTAL SPARE PARTS</b>		:	<b>\$ 31,520.00</b>	
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 29,152.00</b>	
<b>GRAND TOTAL</b>		:	<b>\$ 60,672.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :  
SURVEYED DATE :  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS :

Rasul - Hp 90010568  
10/02/23 @ 1635  
13 clump  
EXCESS: TBA  
Reverse  
Resurvey before paint

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT