

ASS. REC. BY: P. Khan

REF:

3747

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_

Veh No: SMR 8970Z Yr Regn: 2020 Jan  
Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: SMR 8970Z  
at Workshop m/s PREMIUM  
of 24, Altoni Street  
Insured: Ash  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: TBA  
(Cien's Record)  
Make of Veh: \_\_\_\_\_

Make: Audi A5 SB2.0TFSI TFSI c.c. 1984  
Colour: Grey A/C: Insured / Std / NI / NA  
Sp. Reading: 4771 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_

C/No: WUZZZF55KA073043  
Gen. Cond: Good /  Fair / Poor / Burnt  
Steering:  Inorder / Jammed / Leaked / Burnt or  
Brake:  Inorder / Jammed / Leaked / Burnt or  
Modi: Nil /  S/Rim / STD A/Rim or  
Tyre Size: F: 245/40R18  
R: \_\_\_\_\_

(Policy Condition)  
Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S
<input checked="" type="radio"/>	

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or Hankook

Bal. or Market Value: 165K  
IDAC Accident Rport: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

Front \_\_\_\_\_ Rear \_\_\_\_\_  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. 08/02/23 D.O.I. 10/02/23  
Survey held at PREMIUM

CA /  REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or  
REAR N/D  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>REPAIR LIMIT - 104K</u>

Date/Time, File Pass to?  : Prel. Report  
 : Final Report

Days Of Repair: \_\_\_\_\_  
Resurvey No. of Trip: \_\_\_\_\_

1) \_\_\_\_\_ Date/Time, File Return to?  
2) \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Survey Fee:	
Transport:	
\$ = RS =	
Photos	
Other	

Report Format: \_\_\_\_\_  
Lump Sum / B.B. / \_\_\_\_\_



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0164/2023/EQ  
**DATE** : 9-Feb-23  
**WIP** : 62483

**VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/2/2023**

**AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
Attn: Motor Claims Dept  
Tel: **6880 4602** - Fax: **6880 4838**

**OWNER'S NAME** : MR DARA ROK ING  
**ADDRESS** : BLK 440 CHOACHU KANG AVENUE 4  
#06-457  
SINGAPORE 680440  
**TELEPHONE** : HP +65 87155938  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 2070006889-02  
**VEHICLE NO** : **SMR 8970 Z**  
**MODEL CODE** : AUDI A5 SPORTBACK 2.0 TFS  
**MODEL YEAR** : 30/1/2020  
**ENGINE NO** : CVK 087014  
**CHASSIS NO** : WAUZZZF59KA73043  
**MILEAGE** : 47,171  
**DATE IN** : 8-Feb-23  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 8-Feb-23  
**PLACE OF ACCIDENT** : INTERSECTION AT TAMPINES ROAD AND TAMPINES  
INDUSTRIAL DRIVE



55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 8970 Z**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO CARRY OUT FIRST MEASUREMENT ON CAR-O-LINER.	S/N \$	800.00	?
2	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR ASSY. INSPECT FOR FUNCTION AND RENEW ACCORDINGLY.	S/N \$	360.00	/
3	TO RENEW LHS 1/4 GLASS AND REAR WINDSCREEN TO FACILLITATE FENDER RENEWAL.	S/N \$	600.00	/
4	TO INSTALL SOLAR FILM ON AFFECTED GLASS.	S/N \$	400.00	/
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN AND 1/4 GLASS.	S/N \$	<del>200.00</del>	150
6	TO REMOVE AND REINSTALL REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$	280.00	/
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 2,640.00</b>	



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 8970 Z**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$ 1,600.00	/
8	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, SEAT BELTS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,600.00	/
9	TO REMOVE AND REINSTALL REAR EXHAUST SILENCER. RENEW ACCORDING TO DAMAGE AND ALIGN TO POSITION.	S/N \$ 480.00	/
10	TO REMOVE AND REINSTALL REAR SUSPENSION ASSEMBLY FOR CAR-O-LINER REPAIRS.	S/N \$ 3,200.00	?
11	TO SETUP AND PLACE VEHICLE ON CAR-O-LINER.	S/N \$ 2,400.00	?
12	TO DISMANTLE REAR BUMPER AND REAR LID. RE-ALIGN BOTH REAR CHASSIS FRAMES TO SPECIFICATION OF ORIGIN. CUT OUT AND WELD LHS REAR FENDER AND INNER REINFORCEMENT PLATES. RENEW REAR BUMPER AND REAR LID. REINSTALL ALL PARTS REMOVED.	S/N \$ 11,200.00	3500
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 20,480.00</b>	

@500 X 7



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 8970 Z**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
13	TO RESPRAY REAR BUMPER, REAR LID, HINGES, LHS REAR FENDER, DOOR ENTRANCE, DRAIN PANEL, END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	@550x5.5 \$ 5,600.00	3025
14	TO CARRY OUT WHEEL ALIGNMENT.	S/N \$ 240.00	?
15	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 29,152.00</b>	



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 8970 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>torn /</i>	1	\$ 3,187.00	
2	REAR BUMPER FIXING PARTS <i>m /</i>	1	\$ 289.00	
3	REAR BUMPER CHROME TRIM <i>com /</i>	1	\$ 1,206.00	
4	REAR BUMPER SECURING STRIP <i>new /</i>	1	\$ 264.00	
5	REAR BUMPER REFLECTOR - (LH) RH <i>1 pc sum</i>	2	\$ 98.00	
6	REAR PARKING AID SENSOR - INNER / OUTER <i>sum /</i>	<i>1 /</i>	\$ 543.00	
7	REAR PARKING AID SEAL RING <i>m /</i>	4	\$ 11.00	
8	REAR BUMPER REINFORCEMENT BEAM <i>?</i>	1	\$ 1,197.00	
9	REAR BUMPER IMPACT BAR GASKET - LH / RH <i>?</i>	2	\$ 34.00	
10	REAR BUMPER GUIDE SECTION - LH <i>?</i>	1	\$ 52.00	
11	REAR BUMPER GUIDE SECTION <i>(LH) RH com /</i>	2	\$ 54.00	
12	REAR BOOT LID OPENING CONTROL UNIT <i>?</i>	1	\$ 528.00	
13	REAR TAILGATE OPENING SENSOR LINE <i>?</i>	1	\$ 230.00	
14	REAR CONTROL UNIT RETAINER <i>?</i>	1	\$ 10.00	
15	REAR AERIAL RETAINER <i>?</i>	1	\$ 30.00	
16	REAR TELEPHONE AERIAL <i>?</i>	1	\$ 197.00	
17	REAR AERIAL FEMALE CONNECTOR REMOVABLE HOUSING - LH / RH <i>?</i>	2	\$ 46.00	
18	REAR AERIAL WIRE ADAPTER <i>?</i>	1	\$ 392.00	
19	REAR AERIAL WIRE ADAPTER <i>?</i>	1	\$ 392.00	
20	REAR AERIAL FEMALE CONNECTOR REMOVABLE HOUSING <i>?</i>	1	\$ 23.00	
<b>SUB TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 8,783.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT



55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 8970 Z**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR AERIAL FEMALE CONNECTOR REMOVABLE HOUSING ?	1	\$	24.00
22	REAR BUMPER WIRING SET ?	1	\$	751.00
23	REAR LID <i>st/</i>	1	\$	4,342.00
24	AUDI EMBLEM <i>ok/</i>	1	\$	172.00
25	"AS" INSCRIPTION <i>ok/</i>	1	\$	110.00
26	REAR LID ATTACHMENT PARTS ?	1	\$	169.00
27	REAR LID STOP BUFFER - LH / RH ?	2	\$	45.00
28	REAR LID HINGE - LH / RH ?	2	\$	542.00
29	REAR LID FLAP GASKET <i>X</i>	1	\$	278.00
30	REAR LID STRIKER PLATE <i>X</i>	1	\$	86.00
31	PACKING ADHESIVE <i>ok/</i>	1	\$	22.00
32	REAR WINDOW NOT PRETREATED <i>ok/</i>	1	\$	1,379.00
33	WINDOW PRIMER <i>ok/</i>	1	\$	24.00
34	REAR ADDITIONAL BRAKE LIGHT <i>ok/</i>	1	\$	680.00
35	REAR LID TRIM PANEL <i>X</i>	1	\$	565.00
36	REAR OUTER TAIL LIGHT - LH <i>ok/</i>	1	\$	1,344.00
37	REAR OUTER TAIL LIGHT TRIM - LH <i>ok/</i>	1	\$	36.00
38	REAR INNER TAIL LIGHT - LH <i>ok/</i>	1	\$	1,200.00
39	REAR INNER TAIL LIGHT TRIM - LH <i>ok/</i>	1	\$	36.00
40	REAR LID STOP BUFFER	1	\$	23.00
<b>SUB TOTAL SPARE PARTS</b>			<b>:</b>	<b>\$ 11,828.00</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	REAR SIDE PANEL - LH <i>huv</i>	1	\$	4,315.00	
42	REAR VENT TRIM - LH / RH ?	2	\$	153.00	
43	REAR SIDE PANEL CONNECTING PLATE - LH ?	1	\$	78.00	
44	REAR SIDE PANEL REINFORCEMENT - LH ?	1	\$	243.00	
45	REAR D-PILLAR REINFORCEMENT - LH ?	1	\$	323.00	
46	REAR BOTTOM PLATE - LH OUTER ?	1	\$	535.00	
47	REAR WHEEL HOUSING LINER - LH <i>turn</i>	1	\$	322.00	
48	REAR WHEEL HOUSING LINER ATTACHMENT PARTS <i>m</i>	1	\$	187.00	
49	REAR SILENCER HEAT SHIELD - LH ?	1	\$	179.00	
50	REAR CENTRE SILENCER <i>cont?</i>	1	\$	1,327.00	
51	REAR SILENCER - LH <i>st</i>	1	\$	1,318.00	
52	REAR SILENCER DUAL CLIP <i>m</i>	2	\$	121.00	
53	EXHAUST SILENCER BRACKET <i>m</i>	1	\$	48.00	
54	REAR WINDSCREEN SEALANT <i>m</i>	S/N	\$	200.00	
55	1/4 GLASS SEALANT <i>m</i>	S/N	\$	100.00	
56	METAL FILLER POWDER <i>m</i>	S/N	\$	280.00	
57	ACRYLIC SEALANT <i>m</i>	S/N	\$	180.00	
58	CAVITY WAX <i>m</i>	S/N	\$	140.00	
59	STONE CHIP <i>m</i>	S/N	\$	180.00	
60	REAR NUMBER PLATE WITH HOLDER <i>X</i>	S/N	\$	80.00	
61	SUNDRIES ?		\$	600.00	
<b>TOTAL SPARE PARTS</b>		:	\$	<b>31,520.00</b>	
<b>TOTAL LABOUR CHARGES</b>		:	\$	<b>29,152.00</b>	
<b>GRAND TOTAL</b>		:	\$	<b>60,672.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Rasul - Hp 90110568*  
SURVEYED DATE : *10/02/23 @ 1635*  
AUTHORISED DATE :  
EXCESS COST : *13 dump*  
LIABILITY : *EXCESS: TBA*  
REMARKS : *Reverse Resurvey before paint*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	374I
<b>Vehicle Details</b>	
Vehicle No.:	SMR8970Z
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Feb 2023
Vehicle Make:	AUDI
Vehicle Model:	A5 SB 2.0 TFSI S TRONIC (DESIGN)
Primary Colour:	Grey
Manufacturing Year:	2019
Engine No.:	CVK087014
Chassis No.:	WAUZZZF59KA073043
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$38,524.00
Original Registration Date:	30 Jan 2020
First Registration Date:	30 Jan 2020
Transfer Count:	0
Actual ARF Paid:	\$45,934.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jan 2030
PARF Rebate Amount:	\$34,450.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	29 Jan 2030
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$37,705.00
COE Rebate Amount:	\$26,251.00
<b>Total Rebate Amount:</b>	<b>\$60,701.00</b>

# Audi A5 Sportback 2.0A TFSI S-tronic Design

Overview

Financial

Accessories

Similar

Research

Photos

Map

**SUPREME**

DO WHAT YOU LOVE

Price

**\$165,988**

Depreciation 

\$20,530 /yr

[View models with similar depre](#)

Reg Date

30-Jan-2020

(6yrs 11mths 17days COE left)

Mileage

57,000 km (18.8k /yr)

Manufactured 

2019

Road Tax 

\$1,194 /yr

Transmission

Auto

Dereg Value 

\$60,726 as of today (change)

OMV 

\$38,530

COE 

\$37,705

ARF 

\$45,942

Engine Cap

1,984 cc

Power

140.0 kW (187 bhp)

Curb Weight 

1,535 kg

No. of Owners 

1