

ASS. REC. BY: P. Khan

REF: _____

3747

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____

Veh No: SMR 8970Z Yr Regn: 2020 Jan
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or _____

To inspect Vehicle No: SMR 8970Z

Make: Audi A5 SB2.0TFSI TRQ C.C. 1984

at Workshop m/s PREMIUM

Colour: Grey A/C: Insured / Std / NI / NA

of 24, Monol Secur

Sp. Reading: 4771 T/Radio: Insured / Std / NI / NA

Insured: Ash

Eng/No: _____

Policy No. _____

C/No: WUZZZF55KA073043

Claims No. _____

Gen. Cond: Good Fair / Poor / Burnt

Sum Insured: _____ Excess: TBA

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh: _____

Mod: NI / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 245/40R18

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
<input checked="" type="radio"/>	

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

Bal. or Market Value: 165K

TOYO / YOKO or Hankook

IDAC Accident Rport: _____ Consistent? : Yes or No

Front _____ Rear _____

GIA / PR Seen: _____ Consistent? : Yes or No

R/Bal. 6 mm L/Bal. 6 mm

Est. Repairs: _____ days Res.: Yes or No

L/Bal. 6 mm L/Bal. 6 mm

Lum Sum: _____ % 3 Val.: Yes or No

D.O.A. 08/02/23 D.O.I. 10/02/23

CA / REV / REP. / 24 HRS

Survey held at PREMIUM

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop / or

REAR N/D

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>REPAIR LIMIT - 104K</u>

Date/Time, File Pass to? : Prel. Report
 : Final Report

Days Of Repair: _____

1) _____
Date/Time, File Return to?

Resurvey No. of Trip: _____

2) _____

Add Fee: : Site Insp (\$ _____)

Survey Fee:	
Transportation:	
\$ - RS - SE	

Report Format: _____

Lump Sum / I.B.I. () _____

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Photos	
Other	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0164/2023/EQ
DATE : 9-Feb-23
WIP : 62483

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/2/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Tel: **6880 4602** - Fax: **6880 4838**

OWNER'S NAME : MR DARA ROK ING
ADDRESS : BLK 440 CHOA CHU KANG AVENUE 4
#06-457
SINGAPORE 680440
TELEPHONE : HP +65 87155938
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070006889-02
VEHICLE NO : **SMR 8970 Z**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 30/1/2020
ENGINE NO : CVK 087014
CHASSIS NO : WAUZZZF59KA73043
MILEAGE : 47,171
DATE IN : 8-Feb-23
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 8-Feb-23
PLACE OF ACCIDENT : INTERSECTION AT TAMPINES ROAD AND TAMPINES
INDUSTRIAL DRIVE



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 8970 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO CARRY OUT FIRST MEASUREMENT ON CAR-O-LINER.	S/N \$	800.00	?
2	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR ASSY. INSPECT FOR FUNCTION AND RENEW ACCORDINGLY.	S/N \$	360.00	/
3	TO RENEW LHS 1/4 GLASS AND REAR WINDSCREEN TO FACILLITATE FENDER RENEWAL.	S/N \$	600.00	/
4	TO INSTALL SOLAR FILM ON AFFECTED GLASS.	S/N \$	400.00	/
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN AND 1/4 GLASS.	S/N \$	200.00	150
6	TO REMOVE AND REINSTALL REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$	280.00	/
TOTAL LABOUR CHARGES		:	\$ 2,640.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 8970 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$	1,600.00	/
8	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, SEAT BELTS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,600.00	/
9	TO REMOVE AND REINSTALL REAR EXHAUST SILENCER. RENEW ACCORDING TO DAMAGE AND ALIGN TO POSITION.	S/N \$	480.00	/
10	TO REMOVE AND REINSTALL REAR SUSPENSION ASSEMBLY FOR CAR-O-LINER REPAIRS.	S/N \$	3,200.00	?
11	TO SETUP AND PLACE VEHICLE ON CAR-O-LINER.	S/N \$	2,400.00	?
12	TO DISMANTLE REAR BUMPER AND REAR LID. RE-ALIGN BOTH REAR CHASSIS FRAMES TO SPECIFICATION OF ORIGIN. CUT OUT AND WELD LHS REAR FENDER AND INNER REINFORCEMENT PLATES. RENEW REAR BUMPER AND REAR LID. REINSTALL ALL PARTS REMOVED.	@500 X 7 S	11,200.00	3500
TOTAL LABOUR CHARGES		:	\$ 20,480.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 8970 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
13	TO RESPRAY REAR BUMPER, REAR LID, HINGES, LHS REAR FENDER, DOOR ENTRANCE, DRAIN PANEL, END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	@550x5.5 \$ 5,600.00	3025
14	TO CARRY OUT WHEEL ALIGNMENT.	S/N \$ 240.00	?
15	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 29,152.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 8970 Z

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	REAR BUMPER <i>torn /</i>	1	\$	3,187.00	
2	REAR BUMPER FIXING PARTS <i>m /</i>	1	\$	289.00	
3	REAR BUMPER CHROME TRIM <i>com /</i>	1	\$	1,206.00	
4	REAR BUMPER SECURING STRIP <i>neu /</i>	1	\$	264.00	
5	REAR BUMPER REFLECTOR - (LH) RH <i>1 pc sm /</i>	2	\$	98.00	
6	REAR PARKING AID SENSOR - INNER / OUTER <i>sm /</i>	1 /	\$	543.00	
7	REAR PARKING AID SEAL RING <i>m /</i>	4	\$	11.00	
8	REAR BUMPER REINFORCEMENT BEAM <i>?</i>	1	\$	1,197.00	
9	REAR BUMPER IMPACT BAR GASKET - LH / RH <i>?</i>	2	\$	34.00	
10	REAR BUMPER GUIDE SECTION - LH <i>?</i>	1	\$	52.00	
11	REAR BUMPER GUIDE SECTION (LH) RH <i>com /</i>	2	\$	54.00	
12	REAR BOOT LID OPENING CONTROL UNIT <i>?</i>	1	\$	528.00	
13	REAR TAILGATE OPENING SENSOR LINE <i>?</i>	1	\$	230.00	
14	REAR CONTROL UNIT RETAINER <i>?</i>	1	\$	10.00	
15	REAR AERIAL RETAINER <i>?</i>	1	\$	30.00	
16	REAR TELEPHONE AERIAL <i>?</i>	1	\$	197.00	
17	REAR AERIAL FEMALE CONNECTOR REMOVABLE HOUSING - LH / RH <i>?</i>	2	\$	46.00	
18	REAR AERIAL WIRE ADAPTER <i>?</i>	1	\$	392.00	
19	REAR AERIAL WIRE ADAPTER <i>?</i>	1	\$	392.00	
20	REAR AERIAL FEMALE CONNECTOR REMOVABLE HOUSING <i>?</i>	1	\$	23.00	
SUB TOTAL SPARE PARTS		:	\$	8,783.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 8970 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR AERIAL FEMALE CONNECTOR REMOVABLE HOUSING ?	1	\$	24.00
22	REAR BUMPER WIRING SET ?	1	\$	751.00
23	REAR LID <i>st/</i>	1	\$	4,342.00
24	AUDI EMBLEM <i>m/</i>	1	\$	172.00
25	"AS" INSCRIPTION <i>m/</i>	1	\$	110.00
26	REAR LID ATTACHMENT PARTS ?	1	\$	169.00
27	REAR LID STOP BUFFER - LH / RH ?	2	\$	45.00
28	REAR LID HINGE - LH / RH ?	2	\$	542.00
29	REAR LID FLAP GASKET <i>X</i>	1	\$	278.00
30	REAR LID STRIKER PLATE <i>X</i>	1	\$	86.00
31	PACKING ADHESIVE <i>m/</i>	1	\$	22.00
32	REAR WINDOW NOT PRETREATED <i>real/</i>	1	\$	1,379.00
33	WINDOW PRIMER <i>m/</i>	1	\$	24.00
34	REAR ADDITIONAL BRAKE LIGHT <i>real/</i>	1	\$	680.00
35	REAR LID TRIM PANEL <i>X</i>	1	\$	565.00
36	REAR OUTER TAIL LIGHT - LH <i>cal/</i>	1	\$	1,344.00
37	REAR OUTER TAIL LIGHT TRIM - LH <i>sea/</i>	1	\$	36.00
38	REAR INNER TAIL LIGHT - LH <i>cal/</i>	1	\$	1,200.00
39	REAR INNER TAIL LIGHT TRIM - LH <i>nis/</i>	1	\$	36.00
40	REAR LID STOP BUFFER	1	\$	23.00
SUB TOTAL SPARE PARTS			:	\$ 11,828.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
41	REAR SIDE PANEL - LH <i>huv</i>	1	\$	4,315.00
42	REAR VENT TRIM - LH / RH ?	2	\$	153.00
43	REAR SIDE PANEL CONNECTING PLATE - LH ?	1	\$	78.00
44	REAR SIDE PANEL REINFORCEMENT - LH ?	1	\$	243.00
45	REAR D-PILLAR REINFORCEMENT - LH ?	1	\$	323.00
46	REAR BOTTOM PLATE - LH OUTER ?	1	\$	535.00
47	REAR WHEEL HOUSING LINER - LH <i>form</i>	1	\$	322.00
48	REAR WHEEL HOUSING LINER ATTACHMENT PARTS <i>m</i>	1	\$	187.00
49	REAR SILENCER HEAT SHIELD - LH ?	1	\$	179.00
50	REAR CENTRE SILENCER <i>cont?</i>	1	\$	1,327.00
51	REAR SILENCER - LH <i>st</i>	1	\$	1,318.00
52	REAR SILENCER DUAL CLIP <i>m</i>	2	\$	121.00
53	EXHAUST SILENCER BRACKET <i>m</i>	1	\$	48.00
54	REAR WINDSCREEN SEALANT <i>m</i>	S/N	\$	200.00
55	1/4 GLASS SEALANT <i>m</i>	S/N	\$	100.00
56	METAL FILLER POWDER <i>m</i>	S/N	\$	280.00
57	ACRYLIC SEALANT <i>m</i>	S/N	\$	180.00
58	CAVITY WAX <i>m</i>	S/N	\$	140.00
59	STONE CHIP <i>m</i>	S/N	\$	180.00
60	REAR NUMBER PLATE WITH HOLDER <i>X</i>	S/N	\$	80.00
61	SUNDRIES ?		\$	600.00
TOTAL SPARE PARTS		:	\$	31,520.00
TOTAL LABOUR CHARGES		:	\$	29,152.00
GRAND TOTAL		:	\$	60,672.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Rasul - Hp 90110568*
SURVEYED DATE : *10/02/23 @ 1635*
AUTHORISED DATE :
EXCESS COST : *13 clump*
LIABILITY : *EXCESS: TBA*
REMARKS : *Reverse Resurvey before paint*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 374I

Vehicle Details

Vehicle No.: SMR8970Z

Vehicle to be Exported: No

Intended Deregistration Date: 12 Feb 2023

Vehicle Make: AUDI

Vehicle Model: A5 SB 2.0 TFSI S TRONIC (DESIGN)

Primary Colour: Grey

Manufacturing Year: 2019

Engine No.: CVK087014

Chassis No.: WAUZZZF59KA073043

Maximum Power Output: 140.0 kW (187 bhp)

Open Market Value: \$38,524.00

Original Registration Date: 30 Jan 2020

First Registration Date: 30 Jan 2020

Transfer Count: 0

Actual ARF Paid: \$45,934.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 29 Jan 2030

PARF Rebate Amount: \$34,450.00

Intended COE Rebate Details

COE Expiry Date: 29 Jan 2030

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$37,705.00

COE Rebate Amount: \$26,251.00

Total Rebate Amount: \$60,701.00

Audi A5 Sportback 2.0A TFSI S-tronic Design

Overview

Financial

Accessories

Similar

Research

Photos

Map

SUPREME

DO WHAT YOU LOVE

Price

\$165,988

Depreciation 

\$20,530 /yr

[View models with similar depre](#)

Reg Date

30-Jan-2020

(6yrs 11mths 17days COE left)

Mileage

57,000 km (18.8k /yr)

Manufactured 

2019

Road Tax 

\$1,194 /yr

Transmission

Auto

Dereg Value 

\$60,726 as of today (change)

OMV 

\$38,530

COE 

\$37,705

ARF 

\$45,942

Engine Cap

1,984 cc

Power

140.0 kW (187 bhp)

Curb Weight 

1,535 kg

No. of Owners 

1