

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0161/2023/EQ
DATE : 9-Feb-23
WIP : 62589

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/2/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : M/S PREMIUM AUTOMOBILES PTE LTD
ADDRESS : 55 UBI ROAD 1
SINGAPORE 408699
TELEPHONE : HP +65 66090293
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 0999993555-01/1220004602
VEHICLE NO : SNF 9678 M
MODEL CODE : AUDI A6 DESIGN 2.0 TFSI S
MODEL YEAR : 30/6/2022
ENGINE NO : DKY 015955
CHASSIS NO : WAUZZZF21MN097595
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 4-Feb-23
PLACE OF ACCIDENT : UPPER THOMSON ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNF 9678 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	NA? /
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00	?
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00	500
4	TO RESPRAY FRONT BUMPER AND BONNET.	\$ 2,200.00	550
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: \$ 6,072.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 9678 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>de-</i>	1	\$ 3,187.00	
2	FRONT BUMPER FIXING PARTS <i>X</i>	1	\$ 689.00	
3	FRONT BUMPER CLOSING ELEMENT - CENTER <i>X</i>	1	\$ 263.00	
4	FRONT BUMPER ADAPTER - LH / RH <i>?</i>	2	\$ 94.00	
5	FRONT BUMPER REINFORCEMENT - LH / RH <i>?</i>	2	\$ 264.00	
6	FRONT BUMPER GRILLE - LOWER CENTRE <i>X</i>	1	\$ 181.00	
7	FRONT BUMPER CLOSING ELEMENT - LOWER <i>X</i>	1	\$ 248.00	
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>?</i>	2	\$ 1,026.00	
9	FRONT BUMPER AIR GUIDE - LH / RH <i>?</i>	2	\$ 78.00	
10	FRONT BUMPER AIR GUIDE - LH / RH <i>?</i>	2	\$ 62.00	
11	RADIATOR GRILLE <i>cm</i>	1	\$ 2,603.00	
12	RADIATOR GRILLE COVER - CENTER <i>?</i>	1	\$ 65.00	
13	RADIATOR GRILLE COVER CAP <i>?</i>	1	\$ 59.00	
14	RADIATOR GRILLE BRACKET <i>?</i>	1	\$ 111.00	
15	FRONT "360" CAMERA <i>X</i>	1	\$ 1,115.00	
16	FRONT BUMPER FOAM FILLER PIECE <i>?</i>	1	\$ 267.00	
17	FRONT BUMPER REINFORCEMENT BEAM <i>?</i>	1	\$ 1,140.00	
18	FRONT BUMPER SUPPORT - LH / RH <i>?</i>	2	\$ 71.00	
19	FRONT BUMPER BRACKET - LH / RH <i>?</i>	2	\$ 130.00	
20	FRONT BUMPER TOP COVER <i>de-</i>	1	\$ 149.00	
SUB TOTAL SPARE PARTS		:	\$ 11,802.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 9678 M

S/N	PARTS DESCRIPTION	DAMAGED PARTS & PRICES			REMARKS
		QTY	S/NETT		
21	FRONT BUMPER GUIDE SECTION - LH / RH ?	2	\$	106.00	
22	AIR CONDITIONER STICKER X	1	\$	36.00	
23	CAUTION SIGN STICKER X	1	\$	17.00	
24	FRONT PARKING AID SENSOR - INNER / OUTER X	2	\$	598.00	
25	FRONT PARKING AID SEAL RING X	4	\$	11.00	
26	FRONT BUMPER WIRING SET ?	1	\$	648.00	
27	HORN LOW TONE - LH X	1	\$	244.00	
28	HORN HIGH TONE - RH X	1	\$	157.00	
29	HORN BRACKET - LH / RH X	2	\$	112.00	
30	BONNET X	1	\$	5,971.00	
31	BONNET IMPACT PROTECTION - CENTER / LH / RH X	3	\$	99.00	
32	BONNET STRIKER - LH / RH X	2	\$	260.00	
33	BONNET LOCK WITH MICRO-SWITCH - LH / RH X	2	\$	488.00	
34	BONNET RELEASE ELEMENT X	1	\$	69.00	
35	BONNET RELEASE LEVER X	1	\$	16.00	
36	BONNET BOWDEN CABLE - CENTER X	1	\$	67.00	
37	BONNET RELEASE CABLE COVER X	1	\$	12.00	
38	HEADLIGHT MOUNTING - LH / RH ?	2	\$	280.00	
39	HEADLIGHT - LH / RH ?	2	\$	19,424.00	
40	LIFT CYLINDER - LH / RH X	2	\$	460.00	
SUB TOTAL SPARE PARTS		:	\$	29,075.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 9678 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	LIFT CYLINDER BRACKET - LH / RH X	2	\$ 16.00	
42	LIFT CYLINDER HOSE X	1	\$ 208.00	
43	OUTSIDE TEMPERATURE SENSOR BRACKET ?	1	\$ 27.00	
44	RADIATOR AIR GUIDE - LH / RH ?	2	\$ 100.00	
45	RADIATOR AIR GUIDE - UPPER / LOWER ?	2	\$ 78.00	
46	FRONT WHEEL HOUSING LINER - LH / RH X	2	\$ 644.00	
47	FRONT WHEEL SPOILER - LH / RH X	2	\$ 392.00	
48	FRONT NUMBER PLATE Lt ✓	S/N	\$ 60.00	
49	SUNDRIES ?		\$ 400.00	
TOTAL SPARE PARTS		:	\$ 42,802.00	
TOTAL LABOUR CHARGES		:	\$ 6,072.00	
GRAND TOTAL		:	\$ 48,874.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Name - Hg 900106Y
: 10/02/23 @ 1400
: 3 days
: EXCESS: 700
: Revers
: Res before paint

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT