

ASS. REC. BY: R. Paul

REF:

27fw

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNF 9678Mat Workshop m/s Premiumof ALCANTARAInsured: AK

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: TBA

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

2pr

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: 229k

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SNF 9678M Yr Regn: 2022 / JulType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A6 Design 2.0 TFSI c.c. 1984Colour: GREY A/C: Insured / Std / NI / NASp. Reading: 15235 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WAAZ22F21MNO9T595Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/55R18

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 04/02/23D.O.I. 10/02/23Survey held at PremiumDes. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 91K

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

) \$ + RS. \$

) Photos

) Others

Report Format: \_\_\_\_\_

Lum Sum / E.P. / etc

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0161/2023/EQ  
**DATE** : 9-Feb-23  
**WIP** : 62589

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/2/2023**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

**OWNER'S NAME** : M/S PREMIUM AUTOMOBILES PTE LTD  
**ADDRESS** : 55 UBI ROAD 1  
SINGAPORE 408699  
**TELEPHONE** : HP +65 66090293  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 0999993555-01/1220004602  
**VEHICLE NO** : SNF 9678 M  
**MODEL CODE** : AUDI A6 DESIGN 2.0 TFSI S  
**MODEL YEAR** : 30/6/2022  
**ENGINE NO** : DKY 015955  
**CHASSIS NO** : WAUZZZF21MN097595  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 4-Feb-23  
**PLACE OF ACCIDENT** : UPPER THOMSON ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNF 9678 M**

| S/N                         | NATURE OF JOBS                                                                                                                                   | ESTIMATED CHARGES    | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|----------------------------|
| 1                           | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID. | S/N \$ 480.00        | ✓                          |
| 2                           | TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.                                                                           | S/N \$ 800.00        | ?                          |
| 3                           | TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.            | \$ 2,400.00          | 500                        |
| 4                           | TO RESPRAY FRONT BUMPER AND BONNET.                                                                                                              | \$ 2,200.00          | 550                        |
| 5                           | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                   | S/N \$ 192.00        | ✓                          |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                  | <b>: \$ 6,072.00</b> |                            |

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 9678 M**

|                              |                                                  |            | <b>DAMAGED PARTS &amp; PRICES</b> |                |
|------------------------------|--------------------------------------------------|------------|-----------------------------------|----------------|
| <b>S/N</b>                   | <b>PARTS DESCRIPTION</b>                         | <b>QTY</b> | <b>S/NETT</b>                     | <b>REMARKS</b> |
| 1                            | FRONT BUMPER <i>de</i>                           | 1          | \$ 3,187.00                       |                |
| 2                            | FRONT BUMPER FIXING PARTS <i>X</i>               | 1          | \$ 689.00                         |                |
| 3                            | FRONT BUMPER CLOSING ELEMENT - CENTER <i>X</i>   | 1          | \$ 263.00                         |                |
| 4                            | FRONT BUMPER ADAPTER - LH / RH <i>?</i>          | 2          | \$ 94.00                          |                |
| 5                            | FRONT BUMPER REINFORCEMENT - LH / RH <i>?</i>    | 2          | \$ 264.00                         |                |
| 6                            | FRONT BUMPER GRILLE - LOWER CENTRE <i>X</i>      | 1          | \$ 181.00                         |                |
| 7                            | FRONT BUMPER CLOSING ELEMENT - LOWER <i>X</i>    | 1          | \$ 248.00                         |                |
| 8                            | FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>?</i> | 2          | \$ 1,026.00                       |                |
| 9                            | FRONT BUMPER AIR GUIDE - LH / RH <i>?</i>        | 2          | \$ 78.00                          |                |
| 10                           | FRONT BUMPER AIR GUIDE - LH / RH <i>?</i>        | 2          | \$ 62.00                          |                |
| 11                           | RADIATOR GRILLE <i>cr</i>                        | 1          | \$ 2,603.00                       |                |
| 12                           | RADIATOR GRILLE COVER - CENTER <i>?</i>          | 1          | \$ 65.00                          |                |
| 13                           | RADIATOR GRILLE COVER CAP <i>?</i>               | 1          | \$ 59.00                          |                |
| 14                           | RADIATOR GRILLE BRACKET <i>?</i>                 | 1          | \$ 111.00                         |                |
| 15                           | FRONT "360" CAMERA <i>X</i>                      | 1          | \$ 1,115.00                       |                |
| 16                           | FRONT BUMPER FOAM FILLER PIECE <i>?</i>          | 1          | \$ 267.00                         |                |
| 17                           | FRONT BUMPER REINFORCEMENT BEAM <i>?</i>         | 1          | \$ 1,140.00                       |                |
| 18                           | FRONT BUMPER SUPPORT - LH / RH <i>?</i>          | 2          | \$ 71.00                          |                |
| 19                           | FRONT BUMPER BRACKET - LH / RH <i>?</i>          | 2          | \$ 130.00                         |                |
| 20                           | FRONT BUMPER TOP COVER <i>de</i>                 | 1          | \$ 149.00                         |                |
| <b>SUB TOTAL SPARE PARTS</b> |                                                  | <b>:</b>   | <b>\$ 11,802.00</b>               |                |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 9678 M**

| S/N                          | PARTS DESCRIPTION                             | DAMAGED PARTS & PRICES |           |                  | REMARKS |
|------------------------------|-----------------------------------------------|------------------------|-----------|------------------|---------|
|                              |                                               | QTY                    | S/NETT    |                  |         |
| 21                           | FRONT BUMPER GUIDE SECTION - LH / RH ?        | 2                      | \$        | 106.00           |         |
| 22                           | AIR CONDITIONER STICKER <del>X</del>          | 1                      | \$        | 36.00            |         |
| 23                           | CAUTION SIGN STICKER <del>X</del>             | 1                      | \$        | 17.00            |         |
| 24                           | FRONT PARKING AID SENSOR - INNER / OUTER X    | 2                      | \$        | 598.00           |         |
| 25                           | FRONT PARKING AID SEAL RING <del>X</del>      | 4                      | \$        | 11.00            |         |
| 26                           | FRONT BUMPER WIRING SET ?                     | 1                      | \$        | 648.00           |         |
| 27                           | HORN LOW TONE - LH X                          | 1                      | \$        | 244.00           |         |
| 28                           | HORN HIGH TONE - RH X                         | 1                      | \$        | 157.00           |         |
| 29                           | HORN BRACKET - LH / RH X                      | 2                      | \$        | 112.00           |         |
| 30                           | BONNET X                                      | 1                      | \$        | 5,971.00         |         |
| 31                           | BONNET IMPACT PROTECTION - CENTER / LH / RH X | 3                      | \$        | 99.00            |         |
| 32                           | BONNET STRIKER - LH / RH X                    | 2                      | \$        | 260.00           |         |
| 33                           | BONNET LOCK WITH MICRO-SWITCH - LH / RH X     | 2                      | \$        | 488.00           |         |
| 34                           | BONNET RELEASE ELEMENT X                      | 1                      | \$        | 69.00            |         |
| 35                           | BONNET RELEASE LEVER X                        | 1                      | \$        | 16.00            |         |
| 36                           | BONNET BOWDEN CABLE - CENTER X                | 1                      | \$        | 67.00            |         |
| 37                           | BONNET RELEASE CABLE COVER X                  | 1                      | \$        | 12.00            |         |
| 38                           | HEADLIGHT MOUNTING - LH / RH ?                | 2                      | \$        | 280.00           |         |
| 39                           | HEADLIGHT - LH / RH ?                         | 2                      | \$        | 19,424.00        |         |
| 40                           | LIFT CYLINDER - LH / RH X                     | 2                      | \$        | 460.00           |         |
| <b>SUB TOTAL SPARE PARTS</b> |                                               |                        | <b>\$</b> | <b>29,075.00</b> |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 9678 M**

|                             |                                       |     | DAMAGED PARTS & PRICES |         |
|-----------------------------|---------------------------------------|-----|------------------------|---------|
| S/N                         | PARTS DESCRIPTION                     | QTY | S/NETT                 | REMARKS |
| 41                          | LIFT CYLINDER BRACKET - LH / RH X     | 2   | \$ 16.00               |         |
| 42                          | LIFT CYLINDER HOSE X                  | 1   | \$ 208.00              |         |
| 43                          | OUTSIDE TEMPERATURE SENSOR BRACKET ?  | 1   | \$ 27.00               |         |
| 44                          | RADIATOR AIR GUIDE - LH / RH ?        | 2   | \$ 100.00              |         |
| 45                          | RADIATOR AIR GUIDE - UPPER / LOWER ?  | 2   | \$ 78.00               |         |
| 46                          | FRONT WHEEL HOUSING LINER - LH / RH X | 2   | \$ 644.00              |         |
| 47                          | FRONT WHEEL SPOILER - LH / RH X       | 2   | \$ 392.00              |         |
| 48                          | FRONT NUMBER PLATE Lt ✓               | S/N | \$ 60.00               |         |
| 49                          | SUNDRIES ?                            |     | \$ 400.00              |         |
| <b>TOTAL SPARE PARTS</b>    |                                       | :   | <b>\$ 42,802.00</b>    |         |
| <b>TOTAL LABOUR CHARGES</b> |                                       | :   | <b>\$ 6,072.00</b>     |         |
| <b>GRAND TOTAL</b>          |                                       | :   | <b>\$ 48,874.00</b>    |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME  
SURVEYED DATE  
AUTHORISED DATE  
EXCESS COST  
LIABILITY  
REMARKS

: *Ram - Hg 900106Y*  
: *10/02/23 @ 1400*  
: *3 days*  
: *EXCESS: 700*  
: *Revers*  
: *Res before paint*

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT

# Audi A6 Mild Hybrid 2.0A TFSI S-tronic Design

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price \$229,800

Depreciation ⓘ \$21,830 /yr  
View models with similar depre Reg Date 24-Jun-2022  
(9yrs 4mths 11days COE left)

Mileage 10,000 km Manufactured ⓘ 2021

Road Tax ⓘ \$1,194 /yr Transmission Auto

Dereg Value ⓘ \$137,263 as of today (change) Fuel Type Petrol-Electric

COE ⓘ \$106,001 OMV ⓘ \$41,876

Engine Cap 1,984 cc ARF ⓘ \$50,627

Curb Weight ⓘ 1,680 kg Power 140.0 kW (187 bhp)

Type of Vehicle Luxury Sedan No. of Owners ⓘ 1

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 271W

### Vehicle Details

Vehicle No.: SNF9678M

Vehicle to be Exported: No

Intended Deregistration Date: 12 Feb 2023

Vehicle Make: AUDI

Vehicle Model: A6 DESIGN 2.0 TFSI (140 KW)

Primary Colour: Grey

Manufacturing Year: 2021

Engine No.: DKY015955

Chassis No.: WAUZZZF21MN097595

Maximum Power Output: 140.0 kW (187 bhp)

Open Market Value: \$41,905.00

Original Registration Date: 30 Jun 2022

First Registration Date: 30 Jun 2022

Transfer Count: 0

Actual ARF Paid: \$50,667.00

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 29 Jun 2032

PARF Rebate Amount: \$38,000.00

### Intended COE Rebate Details

COE Expiry Date: 29 Jun 2032

COE Category: B - Car-Details at OneMotoring

COE Period(Years): 10

QP Paid: \$106,001.00

COE Rebate Amount: \$99,434.00

Total Rebate Amount: \$137,434.00