

Date: 2/2/2023
 Vehicle No: SND9212J
 Model: TESLA MODEL 3 STANDARD RANGE
 Chassis: 5YJ3F7EA0KF462648
 Reg.Year: 2022

*NOT Ashok
 Army By paint
 2 days*

Third Party Insurer: AIG
 Third Party Veh No: GBH2490P
 Date of Accident: 19/9/2022
 Estimator: VICTOR
 Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1		<i>Re</i> \$763.50
2	FRONT REINFORCEMENT BEAM	1		<i>R</i> \$371.03
3	REAR BUMPER BEAM FOAM	1		<i>Sm</i> \$86.73
4	FRONT BUMPER PARKING SENSOR	1		<i>Pa</i> \$163.55
5	FRONT BUMPER PARKING SENSOR BRACKET	1		<i>r</i> \$4.67
SUB TOTAL				\$1,389.48
LESS 10%				\$138.95
PARTS TOTAL				\$1,250.53

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT LICENSE PLATE WITH HOLDER	1		<i>Re</i> \$75.00
S/N TOTAL				\$75.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR & READJUST REAR ACCIDENT AREA. 200 \$400.00

LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREA. 220 \$400.00

TO TUFF KOTE & UNDERSEAL MATERIALS. *na* \$120.00 X

TO DIAGNOSIS FAULT CODE & RE-CALIBRATE FRONT PARKING SENSOR. \$ 150.00 X

SUNDRIES. \$ 100.00 X

LABOUR TOTAL \$1,170.00

TOTAL \$2,495.53

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Notified by Repairer

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 19/09/2022 18:04 (SGT)
Reported by Driver
Date of Accident 19/09/2022 13:20 (SGT)
Exact Location of Accident 320 Orchard Rd, Singapore 238865
Additional Location Information Marriott Hotel Loading Bay
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SND9212J

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner DHUNSERI PETROCHEM & TEA PTE. LTD
Company Reg No 2XXXXX419H
Email Address dedeeeman@gmail.com
Mobile Phone No (Phone) +65-84455783
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Tesla
Model MODEL 3
Variant Standard Range Saloon
Exact purpose for which vehicle was being used at time of accident Private hire
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 0


INSURANCE COMPANY

Name of Insurance Company EQ Insurance Company Ltd
Policy Number / Cover Note Number DMPPHQ22-001416

DRIVER

Name of Driver DIDI SUFYAN BIN ARWAN
NRIC No SXXXX461B
Date Of Birth 17/04/1981
Occupation Outdoor

ACCIDENT DIAGRAM



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed By Reporting Officer
Mohammad Azaly Bin Abdullah
Witnessed by Reporting Centre
Personnel

19/9/22