

Date: 2/2/2023
 Vehicle No: SND9212J
 Model: TESLA MODEL 3 STANDARD RANGE
 Chassis: 5YJ3F7EA0KF462648
 Reg.Year: 2022

Not whorish
Prummy B4 paint
2 day

Third Party Insurer: AIG
 Third Party Veh No: GBH2490P
 Date of Accident: 19/9/2022
 Estimator: VICTOR
 Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1		<i>Pr</i> \$763.50
2	FRONT REINFORCEMENT BEAM	1		<i>r</i> \$371.03
3	REAR BUMPER BEAM FOAM	1		<i>su</i> \$86.73
4	FRONT BUMPER PARKING SENSOR	1		<i>Pr</i> \$163.55
5	FRONT BUMPER PARKING SENSOR BRACKET	1		<i>su</i> \$4.67
SUB TOTAL				\$1,389.48
LESS 10%				\$138.95
PARTS TOTAL				\$1,250.53

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT LICENSE PLATE WITH HOLDER	1		<i>Pr</i> \$75.00
S/N TOTAL				\$75.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR & READJUST REAR ACCIDENT AREA. *200d* \$400.00

LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREA. *220d* \$400.00

TO TUFF KOTE & UNDERSEAL MATERIALS. *su* \$120.00

TO DIAGNOSIS FAULT CODE & RE-CALIBRATE FRONT PARKING SENSOR. *u* \$150.00

SUNDRIES. *u* \$100.00

LABOUR TOTAL \$1,170.00

TOTAL \$2,495.53