

(08/11/13) wef

ASS. REC. BY: PM

REF:

CC4/AIS230015.11/Rp93

3830

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SOP 99550at Workshop m/s PERFORMANCE MOTOR LTDof 280, KAMPONG ARANK RD

Insured:

AIS

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

259K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SOP 99550

Yr Regn:

2020 / NOVType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

B-M-W X4 XDRIVE 30i MSPT c.c 1998

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

28808

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA2V12070905 2887

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/45R20

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

10/02/23

D.O.I.

22/02/23

Survey held at

PERFORMANCE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair Limit - 168k

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Performance Motors

BMW Dealer



Supplementary

Estimate No. : b1 64979
Date Estimated : 10/02/2023
Prepared By : Jack Ng Guo Ming

Page No. :

- ESTIMATE REPAIR FOR -
Honore Olivier Henri
30 Seranggon Garden Terrace

- ACCOUNT - 224093
Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road
#09-01
Singapore 068897

Singapore 554444

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SDP9955D	WBA2V120709D52887	16/11/2020	X4 xDrive30i	28807

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT <i>ne</i>	2.05	3.00	0.00	6.15
# EXPANDING NUT <i>ne</i>	2.05	2.00	0.00	4.10

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	10.25
Total Labour & Parts (before GST) :	10.25

Performance Motors Limited.
Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W

A Sime Darby Motors Company

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

11 Feb 2023

Estimate No. : b1 64979
Date Estimated : 10/02/2023
Prepared By : Jack Ng Guo Ming

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Honore Olivier Henri
26 Worthing Road

Singapore 554960

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDP9955D	WBA2V120709D52887	16/11/2020	X4 xDrive30i	16797

DESCRIPTION

To replace right front door and make good right front fender

To respray front right door and right front fender

To transfer lock mechanism from old to new door including
conduct check on new door power window system for proper
function. (1 door).

To check electrical wiring

To carry out body cavity preservation.
(Per panel).

Sundries.

VALUE

850 1,700.00

986 2,218.00

504 531.00

168 177.00

112 118.00

80? 150.00

Total Labour 1: 4,894.00

DESCRIPTION

FRT RH DOOR b1

FRT RH DOOR MOULDING (M SPORT X)

FRT RH DOOR WINDOW CAVITY SEAL

FRT RH DOOR WINDOW FRAME COVER (SW

FRT RH DOOR COLUMN B COVER (SW HGL)

(S/L) DOOR WEATHERSTRIP

QTY

PRIC

VALUE

1 1,616.10

1 181.55

1 93.25

1 101.15

1 78.60

1 175.15

1,616.10

181.55

93.25

101.15

78.60

175.15

Total Parts : 2,245.80

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 64979

Page No. : 2 of 5

Date Estimated : 10/02/2023

Prepared By : Jack Ng Guo Ming

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDP9955D	WBA2V120709D52887	16/11/2020	X4 xDrive30i	16797

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 22/02/23 @ 1615 Excess S\$ _____

Surveyor's Name Rahul Sign _____

Surveyor's Tel 90616568 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend 3 days + 1 = 4 days

Reg before part

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed 1 is subject to final approval from Insurance company

Acknowledged by Repairer

Signature: _____

Date: _____



Labour 1	:	4,894.00
Parts	:	2,245.80
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 8%	:	571.18
Grand Total	:	<u>7,710.98</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **