

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC1810L

Make : HYUNDAI

Model : IONIQ(G2)

Date: 03/02/2023

Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT BUMPER COVER <i>scr</i>			\$ 481.10
10	FRT BUMPER CLIPS 2000 <i>nec</i>			\$ 22.00
1	FRT BUMPER SIDE BRACKET LH ? <i>nn</i>			\$ 28.00
1	FRT WHEEL HUB CAP LH <i>scr</i>			\$ 346.40
1	FRT FENDER LH <i>dm</i>			\$ 588.80
1	EMBLEM- BLUE DRIVE LH <i>nec</i>			\$ 26.60
1	FRT DOOR MIRROR ASSY LH <i>scr R</i>			\$ 1,391.70
1	HEADLAMP LH <i>scr</i>			\$ 2,110.30
1	FRT BUMPER SIDE MOULDING LH ? <i>nn</i>			\$ 93.60
1	DAY LIGHT RH ? <i>nn</i>			\$ 642.50
	SUB TOTAL			\$ 5,731.00
	LESS 20%			\$ 1,146.20
	DISCOUNTED TOTAL			\$ 4,584.80
	RENEW ADVERTISEMENT STICKER <i>ml</i>			\$ 200.00
				\$ 200.00
	Labour Charge			
	PANEL BEATING			\$ 1,100.00
	SPRAY PAINTING CHARGE			\$ 900.00
	CHECK ALL LIGHTING			\$ 60.00
	TUFF KOTE			\$ 60.00
	TOTAL LABOUR			\$ 2,120.00
	ESTIMATE TOTAL			\$ 6,904.80

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

T = 3432.13

= 3450.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3 days

L/S

3/3/23 450pm
~~1450~~ 1450