

REPAIR ESTIMATE

LKK -

DATE: 04.02.2023 (Sat)

MODEL: MERCEDES E6

VEHICLE NO.: SHD6665B

INSURANCE: INCOME (LKS)

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
2282-A	Rear Bumper	1		\$1,510.00
0740-G	Rear Bumper Re-Inforcement	1		\$1,150.00
2283-G	Rear Bumper Lower Cover	1		\$175.00
3886-G/3986-G	Rear Bumper Lower Bracket (LH / RH)	2	\$135.00	\$270.00
	Rear Bumper Tow Cover	1		\$175.00
0809-X	BootLid	1		\$2,470.00
2015-G	BootLid - Mercedes Star	1		\$45.00
3998-A	TailLamp RH	1		\$640.00
	SUB TOTAL			\$6,435.00
	LESS 20%			\$1,287.00
	DISCOUNTED TOTAL			\$5,148.00
	Reverse Sensor	1		\$388.00
	S/NETT 10%			\$38.80
	S/NETT TOTAL			\$349.20
	Rear Bumper Mat	1		\$50.00
	NETT TOTAL			\$50.00
	TOTAL SPARE PARTS			\$5,547.20
	<u>Labour Charge</u>			
	Panel Beating			\$1,000.00
	Spray Painting Charge			\$600.00
	Remove/Refix Reverse Sensor			\$120.00
	Towing Fee - no tow chit			-
	TOTAL LABOUR			\$1,720.00
	ESTIMATE TOTAL			\$7,267.20

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanjum 44495749
 WP 6/2/23 C345
 L/S Kesary after repair
 tanjum C (hand) 03
 3 days

3500
 349.20
 50
 1230
 5129.20
 4/5 \$4100 (3 days)