

COMFORTDELGRO ENGINEERING PTE LTD

SAS-KW

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

LKK-

DATE: 06.02.2023INSURANCE: INCOME (LKS)MODEL: Hyundai IoniqMVA: LIM T SVEHICLE NO.: SHD4723E

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
	Rear Bumper	1		\$ 459.40	RY
	Rear Bumper Reinforcement	1		\$ 394.80	RY
	Rear Bumper Reinforcement Brkt RH / LH	2	\$ 55.80	\$ 111.60	RY
	Rear Bumper Centre Moulding	1		\$ 451.25	de
	Rear Bumper Cover Clips	10	\$ 2.20	\$ 22.00	new
	Rear Bumper Tow Cover	1		\$ 98.80	X
	Rear Bumper FogLamp	1		\$ 201.50	X
	Rear Smart Key Antenna	1		\$ 40.50	X
	SUB TOTAL		473.25	\$ 1,779.85	
	LESS 20%			\$ 355.97	
	DISCOUNTED TOTAL		378.60	\$ 1,423.88	
	Reverse Sensor	1		\$ 180.00	X un
	Rear No. Plate With Trim Cover (YELLOW)	1	55	\$ 55.00	bt
	SUB S/NETT			\$ 235.00	
	LESS 10%			\$ 23.50	
	S/NETT TOTAL			\$ 211.50	
	Rear Bumper Mat	1		\$ 50.00	NETT
	SPARE PARTS TOTAL			\$ 1,685.38	
	Labour Charge				
	Panel Beating		630	\$ 400.00	350
	Spray Painting Charge			\$ 300.00	250
	Remove/Refix Reverse Sensor			\$ 120.00	30
	TOTAL LABOUR		1063.60	\$ 820.00	
	ESTIMATE TOTAL		4598.50	\$ 2,505.38	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanjin 9745749
 WP 6/2/23 3:15 pm
 L/S Resurvey after repair
 Tanjin e/Handbook
 2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display Damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No file modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company