

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC 572E
MAKE HYUNDAI
MODEL IONIQ

DATE: 06.02.23
MVA JUMANI
DOA: 04.02.23

INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY			\$459.40
1	REAR BUMPER CENTER MOULDING			\$451.25
1	REAR BUMPER BEAM			\$394.80
10	REAR BUMPER CLIPS			\$22.00
1	ANTENNA SMARTKEY			\$40.50
1	FOG LAMP			\$201.50
1	REAR UNDER LOWER MOULDING			\$155.00
1	TOW COVER			\$98.80
1	REAR BUMPER UNDER LOWER COVER			\$225.00
	SUB TOTAL			\$2,048.25
	LESS 20%			\$409.65
	DISCOUNTED TOTAL			\$1,638.60
	REAR NUMBER PLATE			\$50.00
	REVERSE SENSOR			\$180.00
	ADVERTISEMENT LOGO-FENDER			\$200.00
				\$430.00
	Labour Charge			
	PANEL BEATING			\$400.00
	SPRAY PAINT			\$300.00
	REMOVE / REFIX REVERSE SENSOR			\$50.00
	TOTAL LABOUR			\$750.00
	ESTIMATE TOTAL			\$2,818.60
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

LKK Auto Consultants hence notify

the Repairer of the following:

• To resurvey before/after spray painting

• Parts prices are subject to confirmation

• Third party survey on a "Without Prejudice" basis

• No illegal modification(s) allowed

• Supplementary item(s) must be surveyed and

is subject to final approval from Insurance Company

Date/Time: 06.02.2023 13:59

Page : 1

Team: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 5812113

JC NO.305544764


OWNER CITYCAB PTE LTD 7010070 OWNER NO. 383 SIN MING DRIVE Singapore SINGAPORE 575717 65551188 (P) (O)	REGN NO.	SHC 572E	MILEAGE
	MAKE	HYUNDAI	FUEL E.....1/2.....F
	MODEL	IONIQ(G2)	DATE/TIME IN 04.02.2023 17:50
	YR OF MANU	23.04.2019	TARGET DATE
	CHASSIS CODE	KMHC851CVKU140993	COMPLETION DATE/TIME:

DUNT CARD NO.

JOB DESCRIPTION

Accident Date: 04.02.2023
NATURE: 3P.04.02.23

/NO LABOR CODE DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

to.: SHC 572E JU INCOME

Vehicle No.: SHC 572E

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard

**COMFORTDELGRO
ENGINEERING**

Our Job Ref No : 305544764
Date 08.02.23

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK Fax :
Attn : Mr TAUFIKH
Vehicle Reg No. SHC 572E Date of Accident : 04.02.23

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill 703A **INCOME** **SMZ6432G**
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost**
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% **\$1,250.00**
Final Lumpsum Repair cost
3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature :
Name : JUMANI
Tel : 62148315
Fax : 65468156

Signature :
Name : TAUFIKH
Date :

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	NO		
3. Survey Fees	---	---		
LTA Search Fee	26.75/2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks: