

REC BY: T. J. M.

REF:

NS/MC 23001526/Tvp3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect/Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHK 8228H Yr Regn: 2021, Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nyanderi C.C. 1580

Colour: Yellow A/C: Insured / Std / NI / NA

Sp. Reading: 201584 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMMCS1CVLY 183667

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / SUMI /

TOYO / YOKO, or Worlake

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 5/2/23 D.O.I. 6/2/23

Survey held at Conquest Lodge

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Site Insp (\$ _____)

Interview (\$ _____)

Tech. Insp (\$ _____)

Weekend (\$ _____)

Photos

Others

Lump Sum / L.S. / L.S.

Lump Sum / L.S. / L.S.

Date/Time: 06.02.2023 16:32

Page : 1

Team: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 5812168

JC NO.305544793

OWNER

IS CITYCAB PTE LTD
OWNER NO 7010070
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
65551188 (R) (O)
(P)

DUNT CARD NO.

REGN NO:

SHA8228H

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G3)

DATE/TIME IN 06.02.2023 12:50

YR OF MANU

31.08.2021

TARGET DATE

CHASSIS CODE

KMHC851CVLU183667

COMPLETION DATE/TIME:


JOB DESCRIPTION

Accident Date: 05.02.2023
NATURE: 3P.05.02.23

/NO

LABOR CODE

DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

Io.: SHA8228H

JU INCOME

Vehicle No.:

SHA8228H

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard

REPAIR ESTIMATE*

MODEL	IONIQ
-------	-------

DOA: 05.02.23

INCOME

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Vehicle: The final repair quantum will be determined on the basis of confirmation

• Third party survey report will be on "No Fault" basis

• If needed information(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date: