

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Lim

Date: 14 Feb 2023

Preliminary Advice

Vehicle No	: SMT1227Y	Accident Date	: 07/02/2023
Make	: MERCEDES-BENZ CLA 200	Policy No.	: SP2003907937
Assignment Date	: 13/02/2023	Excess	: S\$700.00
Date of Inspection	: 14/02/2023	Est. Duration of Repair	: 3
Inspection At	: TONG LUCK AUTO PTE LTD (HQ) 160 SIN MING DRIVE, #07-01 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,466.95
Revised Amount	:S\$	2,217.75
Check Items (Estimated)	:S\$	1,896.50
Total	:S\$	4,114.25

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	163,000.00
COE / PARF Rebate	:S\$	54,655.00
Salvage Value	:S\$	
Margin for Repair	:S\$	108,345.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.