



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Website: www.tlauto.com.sg

Email : operation@tlauto.com.sg

UEN: 201700521W GST NO.: 201700521W

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD

79, ROBINSON ROAD #09-01

SINGAPORE 068897

TEL : 67143369

FAX :

ATTN: MOTOR CLAIMS DEPT

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 07/02/2023

TAX INVOICE

NO : AR202304-0055

CLAIM NO : QUOT202302-000036(01)

DATE : 25/04/2023

POLICY NO : SP2003907937

VEH REG : SMT1227Y

MAKE/MODEL : MERCEDES BENZ CLA200
PROGRESSIVE (R18 LED)

CHASIS NO : W1K1183872N081710

ENGINE NO : 26291480298857

REG. DATE : 2019

Final Repair Cost to Vehicle No : SMT1227Y

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Front grille	1	168.00	168.00
2 Front grille centre logo	1	115.00	115.00
3 Front grille beam	1	168.00	168.00
4 Front grille beam moulding	2	58.00	116.00
5 Front grille inner support	1	55.00	55.00
6 Front bumper	1	950.00	950.00
7 Front bumper centre logo	1	62.00	62.00
8 Front bumper reinforcement	1	350.00	350.00
9 Front bumper sponge	1	98.00	98.00
10 Front bumper sensor seal	6	8.00	48.00
11 Front number plate garnish	1	75.00	75.00
			2,205.00
		Add 10%	220.50
			2,425.50
SPECIAL NET			
12 Front grille clips (set)	1	20.00	20.00
13 Front bumper clips (set)	1	50.00	50.00
14 Front number plate	1	40.00	40.00
			110.00
LABOUR			
16 To panel beat and straighten front support panel, front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	250.00	250.00
17 To pull and spray on the accident areas	1	250.00	250.00
18 To check and rectify wiring system	1	20.00	20.00
19 To remove and refit front bumper sensor	1	60.00	60.00
			580.00



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Website: www.tlauto.com.sg

Email : operation@tlauto.com.sg

UEN: 201700521W GST NO.: 201700521W

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD

79, ROBINSON ROAD #09-01
SINGAPORE 068897

TEL : 67143369

FAX :

ATTN: MOTOR CLAIMS DEPT

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 07/02/2023

TAX INVOICE

NO : AR202304-0055

CLAIM NO : QUOT202302-000036(01)

DATE : 25/04/2023

POLICY NO : SP2003907937

VEH REG : SMT1227Y

MAKE/MODEL : MERCEDES BENZ CLA200
PROGRESSIVE (R18 LED)

CHASIS NO : W1K1183872N081710

ENGINE NO : 28291480298857

REG. DATE : 2019

Final Repair Cost to Vehicle No : SMT1227Y

Description	Quantity	Unit Price	Amount
		<u>S\$</u>	<u>S\$</u>
		AMOUNT:	S\$ 3,115.50
		LESS EXCESS:	S\$ 700.00
		TOTAL:	S\$ 2,415.50
		ADD GST @ 8%:	S\$ 193.24
		GRAND TOTAL:	<u>S\$ 2,608.74</u>

SINGAPORE DOLLARS TWO THOUSAND SIX HUNDRED AND EIGHT AND CENTS SEVENTY-FOUR ONLY

TONG LUCK AUTO PTE LTD

E. & O.E.

AUTHORISED SIGNATURE