



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI23001531/Uqy3e2 Date: 21/02/2023	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SNB 5737Z	Veh. Inspected	SLK 7005R	
Policy No.	P10802440R00	Coverage (\$)	0.00	
Claim No.	C10020416 /CD	Excess (\$)	0.00	
Assign From	FRAULEINE KHOO	Assign Date	13/02/2023	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HARRIER ELEGANCE (A)	c.c	1986	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	ZSU600091319	Colour	WHITE	
Odometer	89649 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/65 R17	BRIDGESTONE	7 mm	
L/H Front Tyre	225/65 R17	BRIDGESTONE	7 mm	
R/H Rear Tyre	225/65 R17	BRIDGESTONE	7 mm	
L/H Rear Tyre	225/65 R17	BRIDGESTONE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/02/2023	Inspection Date	13/02/2023	
Survey held at	TLM AUTOMOBILE PTE LTD 1 DEFU LANE 6, DEFU INDUSTRIAL PARK A, SINGAPORE 539365			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		