



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJP 836C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DENTED/CUT	723.30	551.50
1	LH REAR BUMPER RETAINER	SERVICEABLE	178.00	-
	LESS 20% DISCOUNT		-180.26	-110.30
			721.04	441.20
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIP (SN)	NECESSARY	60.00	60.00
			60.00	60.00
	<u>LABOUR</u>			
	TO REMOVE/REFIX REVERSE SENSOR.		50.00	50.00
	TO REPAIR LH REAR FENDER INCLUDING REPLACEMENT OF PARTS.		480.00	250.00
	TO SPRAY PAINT LH REAR FENDER, REAR BUMPER.		600.00	400.00
			1,130.00	700.00
	GRAND TOTAL		1,911.04	1,201.20
RECOMMENDED COST OF REPAIRS				1,201.20

Report Ref No. CS/FCI23001532/Kqy3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.