



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23001532/Kqy3m4 Date: 31/03/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SBS 6409S	Veh. Inspected	SJP 836C
Policy No.	D-22099843MFBP	Coverage (\$)	0.00
Claim No.	D23000528MFBP	Excess (\$)	0.00
Assign From	AINI BINTE	Assign Date	13/02/2023
2. Vehicle Particulars & Condition			
Make & Model	HONDA FIT (A)	c.c	1317
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	GK31344112	Colour	BLACK
Odometer	46956 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	175/70 R14	YOKOHAMA	9 mm
L/H Front Tyre	175/70 R14	YOKOHAMA	9 mm
R/H Rear Tyre	175/70 R14	YOKOHAMA	9 mm
L/H Rear Tyre	175/70 R14	YOKOHAMA	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	10/02/2023	Inspection Date	27/02/2023
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD (HQ) 176 SIN MING DRIVE #01-06/07/13, SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	