

## Xin Yu (LKK Auto)

---

**From:** Simon Ho (LKKAuto)  
**Sent:** Wednesday, March 8, 2023 2:00 PM  
**To:** Xin Yu (LKK Auto)  
**Subject:** Re: File Audit - XD 2973Z & SDS 4514K & SME 4403P

Dear Xin Yu,

Audit check for the following vehicles & findings are as follow :

XD2973Z, found COR range should be 48K to 53K & not economical to repair.

SDS4514K, found REAR BUMPER LOWER COVER PRICE NEED VERIFICATION.

SME4403P, FIND WITHOUT PROBLEM.

Best Regards,

**Simon Ho**

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [simonho@lkkauto.com](mailto:simonho@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

---

**From:** Xin Yu (LKK Auto) <xinyu@lkkauto.com>  
**Sent:** Wednesday, 8 March 2023 12:52 pm  
**To:** Simon Ho (LKKAuto) <SimonHo@lkkauto.com>  
**Subject:** File Audit - XD 2973Z & SDS 4514K & SME 4403P

Dear Simon,

File for audit check.

1. XD 2973Z - CS3/SGK23000864/Rwy3
2. SDS 4514K - CS/SMR23001533/Swy3
3. SME 4403P - CS3/INC23001755/Swy3

Best Regards,

**Xin Yu** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6256-3561 | fax: 6256-4315 | email: [xinyu@lkkauto.com](mailto:xinyu@lkkauto.com) / [sur@lkkauto.com](mailto:sur@lkkauto.com)

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)