

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

20-Feb-23

ESTIMATE REPAIR BILL FOR AUDI A4 REGN NO: SDS 4514 K

1 pc Bootlid
1 pc Rear bumper
1 pc Rear bumper reinforcement
1 pc Rear bumper lower cover

S/Nett

1 set Rear bumper clips
4 pcs Reverse sensor x 4 @ \$334.00
4 pcs Reverse sensor o-ring x 4 @ \$14.00
1 pc Rear number plate with casing

Sundry

To check wiring

To dismantle / replace reverse sensor to new bumper and reset to the same

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear bumper, rear bumper lower cover, end panel, bootlid, etc

To putty and spray painting on rear bumper, end panel, bootlid

To apply rustproofing on the repaired and replaced panels.

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

T = 2695
20% = 539
= 2156
≈ 2150

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Less 10%

Acknowledged by Repairer

Signature:

Date:

\$ 2,333.78 Dent R
\$ 2,000.56 Cut - 1400
\$ 1,200.66 ? X NV
\$ 670 999.78 Scr ?
\$ 6,534.78
\$ 653.48
\$ 5,881.30
T = 2070
10% = 207
\$ 168.00 X NV
\$ 1,336.00 X NV
\$ 72.00 X NV
\$ 50.00 X NN
\$ 50.00 X NN
\$ 50.00 30
\$ 150.00 30
\$ 180.00 X NV
\$ 1,000.00 300
\$ 900.00 400
\$ 80.00 X NV
\$ 9,917.30

3 days

LCB

21/2/23

4pm
1hr