

Xin Yu (LKK Auto)

From: Simon Ho (LKKAuto)
Sent: Tuesday, March 21, 2023 1:06 PM
To: Xin Yu (LKK Auto)
Subject: Re: File Audit - SDS 4514K - CS/SMR23001533/Swy3

Dear Xin Yu,

Audit check done for SDS4514K without problem.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Xin Yu (LKK Auto) <xinyu@lkkauto.com>
Sent: Tuesday, 21 March 2023 11:42 am
To: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>
Subject: RE: File Audit - SDS 4514K - CS/SMR23001533/Swy3

Dear Simon,

File for audit check. Irfan re-uploaded the amended estimate in view.

Best Regards,

Xin Yu | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | fax: 6256-4315 | email: xinyu@lkkauto.com / sur@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>
Sent: Wednesday, March 8, 2023 2:00 PM
To: Xin Yu (LKK Auto) <xinyu@lkkauto.com>
Subject: Re: File Audit - XD 2973Z & SDS 4514K & SME 4403P

Dear Xin Yu,

Audit check for the following vehicles & findings are as follow :

XD2973Z, found COR range should be 48K to 53K & not economical to repair.

SDS4514K, found REAR BUMPER LOWER COVER PRICE NEED VERIFICATION.

SME4403P, FIND WITHOUT PROBLEM.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Xin Yu (LKK Auto) <xinyu@lkkauto.com>

Sent: Wednesday, 8 March 2023 12:52 pm

To: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>

Subject: File Audit - XD 2973Z & SDS 4514K & SME 4403P

Dear Simon,

File for audit check.

1. XD 2973Z - CS3/SGK23000864/Rwy3
2. SDS 4514K - CS/SMR23001533/Swy3
3. SME 4403P - CS3/INC23001755/Swy3

Best Regards,

Xin Yu | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | fax: 6256-4315 | email: xinyu@lkkauto.com / sur@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)