



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGE 7272B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	DISTORTED	661.00	661.00
1	REAR TAILLAMP - RH	CRACKED	565.00	565.00
1	REAR BUMPER RED REFLECTOR - RH	NOT NECESSARY	49.00	-
	LESS 20% DISCOUNT		-255.00	-245.20
			1,020.00	980.80
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	50.00	-
			50.00	-
	<b><u>LABOUR</u></b>			
	SPRAY PAINTING.		280.00	200.00
	LABOUR CHARGE.		450.00	200.00
	TUFF COAT.	NOT NECESSARY	80.00	-
			810.00	400.00
	<b>GRAND TOTAL</b>		<b>1,880.00</b>	<b>1,380.80</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,380.80</b>

Report Ref No. CS/FCI23001534/Uny3m4

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.