

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Khong Lin Hui Lynn

Date: 19 Jun 2023

**Preliminary Advice**

Insured Vehicle No : SNG5137D  
TP Vehicle No : SLQ2423T  
Make : MERCEDES-BENZ C180  
Date of Inspection : 28/03/2023  
Inspection At : CHENG HOE MOTOR PTE LTD (YISHUN)  
BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A  
SINGAPORE 768761

Accident Date : 31/01/2023  
Assignment Date : 13/02/2023  
Est. Duration of Repair : 4

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,200.90
Revised Amount	:S\$	3,225.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,225.00
 Lump Sum Repair	 :S\$	 2,750.00

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

(       )     The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(   X   )     Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.