



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNG 621E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR FENDER RH	TO REPAIR SEE LABOUR	3,400.00	-
1	REAR FENDER INNER SHIELD RH	NOT NECESSARY	210.00	-
10	REAR FENDER INNER SHIELD CLIP	NOT NECESSARY	80.00	-
1	REAR BUMPER	SCRATCHED	2,800.00	2,200.00
1	REAR BUMPER SIDE RETAINER RH	NOT NECESSARY	120.00	-
1	REAR BUMPER SENSOR	NOT NECESSARY	80.00	-
10	REAR BUMPER CLIP	NECESSARY	100.00	30.00
1	TAIL LAMP RH	NOT NECESSARY	850.00	-
1	TYRE RIM REAR RH	CUT	5,020.00	3,492.69
	LESS 10% DISCOUNT		-1,266.00	-572.27
			11,394.00	5,150.42
<u>SPECIAL NETT ITEMS</u>				
1	WINDSCREEN SEALANT (SN)	NOT NECESSARY	50.00	-
1	BODY SEALANT (SN)	NOT NECESSARY	50.00	-
1	PIRELLI P ZERO 265/35R20 (SN) (ADDITIONAL) (70%)	CUT	420.00	294.00
			520.00	294.00
<u>LABOUR</u>				
	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER RH.		1,600.00	400.00
	TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS.	NOT NECESSARY	200.00	-
	TO REMOVE & REFIT QUARTER GLASS RH.		100.00	100.00
	TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)	NOT NECESSARY	250.00	-
	TO SPRAY PAINT ON THE AFFECTED AREAS.		1,000.00	400.00
	TO REMOVE, RENEW & REFIT REAR RH TYRE. (ADDITIONAL)		30.00	30.00
			3,180.00	930.00
GRAND TOTAL			15,094.00	6,374.42

Report Ref No. CS/FCI23001537/Wny3e2



RECOMMENDED COST OF REPAIRS			6,374.42
-----------------------------	--	--	----------

Report Ref No. CS/FCI23001537/Wny3e2

MUHAMMAD AKID BIN MOHAMED KAMAL

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.