



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23001537/Wny3e2 Date: 23/06/2023  Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SMB 1329G	Veh. Inspected	SNG 621E
Policy No.	D-22099187MFBP	Coverage (\$)	0.00
Claim No.	D23000546MFBP	Excess (\$)	0.00
Assign From	AINI BINTE	Assign Date	13/02/2023
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	MERCEDES BENZ E635	c.c	3982
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	W1K2132892A974997	Colour	BLACK
Odometer	9631 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	295/30Z R20	PIRELLI	6 mm
L/H Front Tyre	295/30Z R20	PIRELLI	6 mm
R/H Rear Tyre	295/30Z R20	PIRELLI	6 mm
L/H Rear Tyre	295/30Z R20	PIRELLI	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	11/02/2023	Inspection Date	17/02/2023
Survey held at	160 Sin Ming Drive #06-03 Autocity		
Repairer	MBM WHEELPOWER PTE LTD		
<b>5a. Remarks</b>			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	