

EST

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: FCI
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$460K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 03 days Res.: Yes or No
 Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SNG 621 E Yr Regn: 10/05/2021
 Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Mercedes Benz E63S cc 3982
 Colour: Black A/C: Insured / Std / Nil / NA
 Sp. Reading: 9631 T/Radio: Insured / Std / Nil / NA
 Eng/No: 17798060143142
 C/No: W1K2137392A9749 *97
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Mod: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 295/30 ZR20
 R: 295/30 ZR20
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / R / SUMI /
 TOYO / YOKO or _____

Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 11/02/2023 D.O.I. 17/02/2023 1500
 Survey held at NBM wheelpower
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Balance: 113.3M
	Yearly: \$40K
	ARF 50%: \$84,765
	MV: \$460K
	LTA: \$213,355
	NV: \$246,612

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1) _____
 Date/Time, File Return to?

2) _____

Report Format :

Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation: _____

\$ + RS \$ _____

Photos

Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	875C
Vehicle Details	
Vehicle No.:	SNG621E
Vehicle to be Exported:	Yes
Intended Deregistration Date:	14 Feb 2023
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E63S AMG ESTATE
Primary Colour:	Black
Manufacturing Year:	2021 ✓
Engine No.:	17798060143142
Chassis No.:	W1K2132892A974997
Maximum Power Output:	450.0 kW (603 bhp)
Open Market Value:	\$104,332.00
Original Registration Date:	10 May 2021 ✓
First Registration Date:	21 Jul 2022
Transfer Count:	①
Actual ARF Paid:	\$169,531.00 ✓
Intended PARF Rebate Details	
PARF Eligibility:	Yes ✓
PARF Eligibility Expiry Date:	09 May 2031
PARF Rebate Amount:	\$127,148.00
Intended COE Rebate Details	
COE Expiry Date:	20 Jul 2032 ✓
COE Category:	B - Car-Details at OneMotoring
COE Period(Years):	10
QP Paid:	\$107,800.00
COE Rebate Amount:	\$86,240.00
Total Rebate Amount:	\$213,388.00 ✓

The information contained herein is correct as at 14 Feb 2023

OK

MBM WHEELPOWER PTE. LTD.

YOUR REF.: SMB1329G


OUR REF.: SNG621E

TO: FIRST CAPITAL

CC: MOTOR CLAIMS DEPARTMENT

FAX:

ESTIMATE FOR VEHICLE NO.: SNG621E



DATE: 17/2/2023
FROM: Lee Shirley
FAX: 64525333
CONTACT: 86865188
MAKE & MODEL: MERCEDES E63S AMG
CHASSIS NO.: W1K2132892A974997
ENGINE NO.: 17798060143142
YEAR MADE: 2021
ACCIDENT DATE: 11 February 2023

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	REAR FENDER RH		1	\$ SCR 3,400.00 R
2	REAR FENDER INNER SHIELD RH		1	\$ 210.00 ?
3	REAR FENDER INNER SHIELD CLIP		10	\$ 80.00 ?
4	REAR BUMPER		1	\$ 2379 SCR 2,800.00 X1
5	REAR BUMPER SIDE RETAINER RH		1	\$ 120.00 ?
6	REAR BUMPER SENSOR		1	\$ 80.00 ?
7	REAR BUMPER CLIP		10	\$ NEC 100.00 X3
8	TAIL LAMP RH		1	\$ 850.00 ?
9	TYRE RIM REAR RH		1	\$ 5120.00 OUT DNT 5,020.00 ✓
TOTAL:				\$ 12,660.00
LESS 10%:				\$ (1,266.00)
PARTS TOTAL:				\$ 11,394.00

SPECIAL NETT

WINDSCREEN SEALANT
BODY SEALANT

1 \$ 50.00 X
1 \$ 50.00 X

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS

\$ 400 1,600.00

TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS

\$ 200.00 X

TO REMOVE & REFIT QUARTER GLASS RH

\$ 100.00 ✓

TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)

\$ 250.00 X

TO SPRAY PAINT ON THE AFFECTED AREAS

\$ 400 1,000.00

TOTAL: \$ 14,644.00

7% GST: \$ 1,025.08

GRAND TOTAL: \$ 15,669.08

Akid Kamal (Lkk)

Dos

8700 5631

17/02/2023

03 days

1509hrs

MBM WHEELPOWER PTE. LTD.
160 SIN MING DRIVE, #06-02
SIN MING AUTOCITY
t 6262 8888 f 6452 5333
COMPANY REG. NO.: 200204110W