

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI23001541/TVP3M4**Date:** 20/02/2023**REFERENCE****Insured/Claimant:** SOO GUICHENG **Policy No:** DMPCSNW00178682200**Date of Loss:** 03/02/2023 **Nature of Claim:** OD **Claim No:** SNM23D200912/C01/TOHHS**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: SLC3330U
Make & Model: VOLKSWAGEN GOLF R, 2.0 5DR 5K1RX7 (A) **Engine No:** CDL043803
Reg. Date: 10/02/2011 (Man. Year: 2010) **Chassis No:** WVVZZZ1KZBW173016
Colour: White **Odometer:** 0 km
Engine Capacity: 1984 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 225/40R18 **Rear Tyre Size:** 225/40R18
Front Left Side: Bridgestone 6 mm **Rear Left Side:** Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm **Rear Right Side:** Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	0.00	0.00	0.00	
- Excess (\$\$)	0.00	1,000.00	-1,000.00	
Nett Amount (\$\$)	0.00	-1,000.00	1,000.00	

INSPECTION

Date of Assignment: 13/02/2023 **Present Location:** Century Motors Pte Ltd (HQ)
Date Inspected: 14/02/2023 **Inspected At:** CENTURY MOTORS PTE LTD
6 MARSILING LANE SINGAPORE 739145
Estimated Period of Repair: 0.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$110,000.00
OMV :	\$38,795.00
PARF Rebate (1) :	\$0
Quota Premium Paid :	\$40,714.00
COE Rebate (2) :	\$32,140.00
Total Rebate (1) + (2) = :	\$32,140.00

The total amount incurred will be Market Value \$110,000.00 minus Total Rebate \$32,140.00 = \$77,860.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Feb 2023)
Parts:	144	VOLKSWAGEN GOLF R 2.0 5DR 5K1RX7 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC3330U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >