



SINGAPORE CIVIL DEFENCE FORCE

## FIRE REPORT

<b>1. GENERAL INFORMATION</b>		
INCIDENT NO.: /20230203/0201	LOCATION OF FIRE:  Parking lot at level 4, Enterprise Hub, 48 Toh Guan Road East Singapore 608586	
FIRE REPORTED ON: 03 February 2023		
TIME OF CALL: 06:55:12 hrs		
STATION COVERAGE: Clementi Fire Station		
<b>2. INCIDENT INFORMATION</b>		
FIRE INVOLVED: The engine compartment of a Volkswagen Car (SLC3330U).		
METHOD OF EXTINGUISHMENT: By SCDF crew using a hose reel jet from a fire appliance.		
PROBABLE CAUSE OF FIRE: Accidental (Electrical origin at the engine compartment).		
DAMAGE OBSERVED*: As a result of the fire, the engine compartment of the car was damaged. Other parts of the car sustained heat, smoke and water damage.		
<b>3. FATALITY/INJURY INFORMATION</b>		
NAME	NRIC/FIN	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL
<b>REPORT ISSUED BY:</b> NICK LI KEJING for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE		

*\*This is based on observations made by the fire investigator incidental to his/her investigation to determine the cause and origin of the fire, and is not to be taken as an exhaustive list of damage caused by the fire.*

*This is a computer generated report. No signature is required.*