

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Alfred Toh

Date: 15 Feb 2023

Preliminary Advice

Vehicle No	: SLC3330U	Accident Date	: 03/02/2023
Make	: VOLKSWAGEN GOLF	Policy No.	: DMPCSNW00178682200
Assignment Date	: 13/02/2023	Excess	: S\$1,000.00
Date of Inspection	: 14/02/2023	Est. Duration of Repair	: 0
Inspection At	: CENTURY MOTORS PTE LTD (HQ) 2 PANDAN CRESENT, INCHAPE CENTRE LEVEL 10 SINGAPORE 128462		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	Total Loss
Revised Amount	:S\$	Total Loss
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	110,000.00
COE / PARF Rebate	:S\$	32,140.00
Salvage Value	:S\$	
Margin for Repair	:S\$	77,860.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :