

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

13 FEB 2023

Estimate No. : b1 64986
Date Estimated : 11/02/2023
Prepared By : Foong Shiuh Jye

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Cheng Zhi Hong Kevin
320 Bukit Batok St 33
#02-60

Singapore 650320

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGQ1297G	WBA8E36050NU82056	26/04/2018	318i	38423

DESCRIPTION

To replace bumper rear panel and attachments
To repair boot lid

To spray paint bumper rear panel and boot lid

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct check for
proper function.

To check electrical wiring system and lighting at the
rear section for proper function.

Sundries.

VALUE

1275 ~~850~~ 2,550.00

1826 1,923.00

168 177.00

168 177.00

80 ? 150.00

Total Labour 1: 4,977.00

DESCRIPTION

✓RR BUMPER BOTTOM REINFORCEMENT

✓REAR BUMPER CARRIER (ECE) ? xaa

REAR BUMPER LH SIDE GUIDE ? xaa

✓REAR BUMPER PANEL PRIMED (LINES) de

SET MOUNTING PDC/PMA SENSOR REAR ? xaa

REAR SILENCER HEAT SHIELD ? xaa

(DG/SL) ADHESIVE SET K6 aa

QTY

PRIC

VALUE

1 119.90

119.90

1 491.65

491.65

1 155.80

155.80

1 1,183.90

1,183.90

1 71.60

71.60

1 76.90

76.90

1 53.05

53.05

Total Parts : 2,152.80

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 64986
Date Estimated : 11/02/2023
Prepared By : Foong Shiuh Jye

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGQ1297G	WBA8E36050NU82056	26/04/2018	318i	38423

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 27/02/23 @ 1328 Excess S\$ _____

Surveyor's Name Rasul Sign _____

Surveyor's Tel 90010068 Authorised Yes / No

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No Yes PML Yes / No No

Surveyor's E-mail _____

Number of working Days Recommend 4 days



Labour 1	:	4,977.00
Parts	:	2,152.80
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 8%	:	570.38
Grand Total	:	<u>7,700.18</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **