

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



**HD PERFECT
AUTOWORK PTE LTD**

DATE : 13.02.2023

TO : **HSBC** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLL8242K**
MODEL : **HONDA VEZEL**
DATE OF ACCIDENT : 11.02.2023
TIME OF ACCIDENT : 11:50 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT WHEEL RIM LH	1	\$ 1,450.00	\$ 1,450.00
2	FRONT ABS SENSOR LH	1	\$ 180.00	\$ 180.00
3	FRONT SHOCK ABSORBER LH	1	\$ 586.50	\$ 586.50
4	FRONT LOWER ARM LH	1	\$ 474.70	\$ 474.70
5	FRONT KNUCKLE ARM LH	1	\$ 461.70	\$ 461.70
6	FRONT KNUCKLE ARM INNER BEARING LH	1	\$ 262.00	\$ 262.00
7	FRONT WHEEL HUP LH	1	\$ 379.40	\$ 379.40
8	FRONT LINKAGE LH	1	\$ 65.00	\$ 65.00
9	FRONT FENDER ARCED GARNISH LH	1	\$ 163.00	\$ 163.00
10	FRONT MUDFLAP LH	1	\$ 151.40	\$ 151.40
11	FRONT DOOR LH	1	\$ 950.00	\$ 950.00
12	FRONT DOOR OUTER MOULDING LH	1	\$ 87.00	\$ 87.00
13	FRONT DOOR HINGE LH	2	\$ 55.00	\$ 110.00
14	FRONT DOOR WEATHER STRIP LH	1	\$ 127.00	\$ 127.00
15	FRONT DOOR INNER LOCK LH	1	\$ 262.00	\$ 262.00
16	FRONT DOOR LOCK CATCH LH	1	\$ 27.00	\$ 27.00
17	FRONT DOOR INNER TRIM BOARD LH	1	\$ 650.00	\$ 650.00
18	FRONT DOOR REGULATOR LH	1	\$ 215.00	\$ 215.00
19	FRONT DOOR POWER WINDOW MOTOR LH	1	\$ 400.00	\$ 400.00
20	FRONT DOOR FRAME WEATHER STRIP LH	1	\$ 135.00	\$ 135.00

TO : **HSBC** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLL8242K**
 MODEL : **HONDA VEZEL**
 DATE OF ACCIDENT : 11.02.2023
 TIME OF ACCIDENT : 11:50 HOURS

21	FRONT DOOR SPEAKER LH	1	\$ 165.00	\$ 165.00
22	FRONT DOOR PILLAR LH (OUTER)	1	\$ 933.00	\$ 933.00
23	FRONT DOOR BLACK STICKER LH	1	\$ 95.00	\$ 95.00
24	SIDE SKIRT LH	1	\$ 650.00	\$ 650.00
25	REAR DOOR LH	1	\$ 1,135.00	\$ 1,135.00
26	REAR DOOR SPEAKER LH	1	\$ 190.00	\$ 190.00
27	REAR DOOR HINGE LH	2	\$ 55.00	\$ 110.00
28	REAR DOOR INNER LOCK LH	1	\$ 285.00	\$ 285.00
29	REAR DOOR LOCK CATCHER LH	1	\$ 25.00	\$ 25.00
30	REAR DOOR INNER TRIM LH	1	\$ 725.00	\$ 725.00
31	REAR DOOR WEATHER STRIP LH	1	\$ 145.00	\$ 145.00
32	REAR DOOR POWER WINDOW MOTOR C/W REGULATOR LH	1	\$ 490.00	\$ 490.00
33	REAR DOOR FRONT RUBBER LH	1	\$ 210.00	\$ 210.00
34	REAR DOOR OUTER STRIP LH	1	\$ 110.00	\$ 110.00
35	REAR DOOR STICKER (BLACK) LH	1	\$ 105.00	\$ 105.00
36	REAR DOOR FRAME WEATHER STRIP LH	1	\$ 170.00	\$ 170.00
37	REAR FENDER ARCDED GARNISH LH	1	\$ 165.00	\$ 165.00
38	REAR WHEEL MUDFLAP LH	1	\$ 151.40	\$ 151.40
39	REAR WHEEL RIM LH	1	\$ 1,450.00	\$ 1,450.00
40	REAR ABS SENSOR LH	1	\$ 430.00	\$ 430.00
41	REAR AXLE	1	\$ 1,670.00	\$ 1,670.00
42	REAR SHOCK ABSORBER LH	1	\$ 398.00	\$ 398.00
43	REAR WHEEL HUP COME WITH BEARING LH	1	\$ 435.00	\$ 435.00
44	REAR BUMPER SIDE LH	1	\$ 230.00	\$ 230.00
45	REAR BUMPER SIDE RETAINER	2	\$ 57.00	\$ 114.00

TOTAL PRICE	\$ 17,723.10
LESS 20%	\$ 3,544.62
SUB TOTAL PRICE	\$ 14,178.48

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	SIDE SKIRT CLIP LH	1	\$ 80.00	\$ 80.00
2	FRONT FENDER INNER COWLING CLIP LH (SET)	1	\$ 50.00	\$ 50.00
3	FRONT FENDER ARCDED GARNISH CLIP LH (SET)	1	\$ 50.00	\$ 50.00

TO : **HSBC** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLL8242K**
 MODEL : **HONDA VEZEL**
 DATE OF ACCIDENT : 11.02.2023
 TIME OF ACCIDENT : 11:50 HOURS

4	FRONT DOOR TRIM BOARD CLIP LH (SET)	1	\$ 80.00	\$ 80.00
5	REAR FENDER COWLING CLIP LH (SET)	1	\$ 80.00	\$ 80.00
6	REAR FENDER ARCED GARNISH CLIP LH (SET)	1	\$ 50.00	\$ 50.00
7	REAR DOOR INNER TRIM CLIP LH (SET)	1	\$ 80.00	\$ 80.00
8	WHEEL TYRE LH	2	\$ 580.00	\$ 1,160.00
9	REAR BUMPER CLIP(SET)	1	\$ 80.00	\$ 80.00
10	DOOR VISOR	1	\$ 250.00	\$ 250.00
11	BRAKE OIL	1	\$ 50.00	\$ 50.00

TOTAL \$ 2,010.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	
3	TUFF COAT	\$ 250.00	
4	WIRING CHECK	\$ 120.00	
5	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	
6	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	
7	TO PRESS FRONT WHEEL BEARING	\$ 40.00	
8	FOUR WHEEL ALIGNMENT	\$ 120.00	
9	REMOVE & REFIX AUDIO SPEAKER	\$ 120.00	
10	TRANSFER FRONT DOOR MECHANISM	\$ 80.00	
11	REMOVE & REINSTALL FRONT WINDOW GLASS	\$ 60.00	

TO : **HSBC** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLL8242K**
MODEL : **HONDA VEZEL**
DATE OF ACCIDENT : 11.02.2023
TIME OF ACCIDENT : 11:50 HOURS

12	CONDUCT WATER LEAKAGE TEST	\$ 80.00	
13	TRANSFER REAR DOOR MECHANISM	\$ 80.00	
14	REMOVE & REINSTALL REAR WINDOW GLASS	\$ 60.00	
15	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 650.00	
16	TO PRESS REAR WHEEL BEARING	\$ 80.00	
17	RESET ABS LIGHT	\$ 350.00	
18	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 280.00	

TOTAL \$ 6,770.00

TOTAL PARTS COST : \$ 16,188.48
TOTAL LABOUR COST : \$ 6,770.00
TOTAL REPAIR COST : \$ 22,958.48

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787