

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 015/IC/TCAC/SAY/2023
DATE : 11-FEB-2023

ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD #09-01

S(068897)
TEL : 63954779/67143369
FAX : 63953768
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : LEE BENG HWEI
ADDRESS : BLK 105 ALJUNIED CRESCENT
#12-227
S(380105)
TELEPHONE NO : 96353576

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 2100454169
VEHICLE NO : SDF5338P
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2233362A
CHASSIS NO : SJNFEAJ11U1583289
MILEAGE : 166331 KM
DATE IN : 11/02/2023
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH
ACCIDENT DATE : 11/02/2023

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SDF5338P

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS	60.00	✓
2 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	✓
3 RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	110.00	✓
4 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	200.00	✓
5 ZZ/001	CONDUCT 3RD PARTY CLAIM ALLIANZ DATE:11/02/2023 TIME:1240 LOCATION:CTE TOWRDS CITY		
6 ZZ/002	REPAIR/REPLACE REAR BUMPER,END PANEL,TAILGATE, FLOOR PAN, LH FENDER & RH FENDER	2340.00	1170 ✓
7 ZZ/003	RESPRAY REAR BUMPER,END PANEL,TAILGATE, FLOORPAN, RH FENDER & LH FENDER	1500.00	750 ✓
8 ZZ/004	CONDUCT REAR LIGHTING TEST	48.00	✓
9 ZZ/005	SUPPLY/INSTALL REAR WINDSCREEN TINTED FILM	144.00	✓
10 ZZ/006	QC & CONSULT CHECK		
11 ZZ/007	CARWASH & VACUUM		
12 ZZ/008	REMOVE/REFIX REAR WINDSCREEN	240.00	✓
13 ZZ/009	TRANSFER TAILGATE MECHANISM TO NEW TAILGATE	120.00	✓
14 ZZ/10	SUPPLY REVERSE SENSOR 4 EYE SET	360.00	✓
TOTAL LABOUR CHARGES		5242.00	3322 ✓

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SDF5338P

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 PANEL-REAR UPPER but ? xan	G9110-4EAMA	573.80		
2 STAY ASSY-REAR RH ? xan	H5210-4EAMA	152.40		
3 STAY ASSY-REAR LH ? xan	H5211-4EAMA	152.40		
4 RUBBER-DUM m/	G2716-89901	68.90		✓
5 A FIN BACK DOOR ? xan	90810-4ESOH	380.00		
6 GLASS-TAIL GATE m/ photo/	90300-4EAOB	1174.80		✓
7 WEATHER STRIP m/	90830-4EAOA	198.40		✓
8 DOOR BACK bt/	K0100-4EAAC	3636.60		✓
9 STRIKER-TAIL GA xan	90570-4EAOA	37.60		
10 A LOCK LIFT ? xan	90502-4EAOB	205.50		
11 RETAINER-BUMPER LH ? xan	79185-4EAOA	27.80		
12 RETAINER-BUMPER RH x xan	79184-4EAOA	27.80		
13 ENERGY ABSORBER ? xan	85090-4EAOB	168.10		
14 FINISHER-REAR TOW COVER cul/	85071-4EAOA	22.40		✓
15 FASCIA-RR BUMP de/	85022-4EAOH	946.50		✓
16 REINF-BUMPER RR ? xan	H5030-4EAMA	746.20		
17 LAMP COMB RR, LH TAILGATE xan	26555-4EA5D	274.80		
18 COMB LAMP RR RH TAILGATE xan	26550-4EA5C	356.10		
19 LAMP COMB RR, LH BODY xan	26555-4EAOA	412.10		
20 LAMP COMB RR, RH BODY x an	26550-4EAOA	412.10		
21 ORNAMENT-BACK DOOR LETTERING m/	90892-4EAOA	101.90		✓
22 EMBLEM-REAR ? m/	90890-4EAOA	70.00		✓

SUB TOTAL
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)

GRAND TOTAL

6219.50
20%
4975.60

10146.20	0.00	0.00
2029.24	0.00	0.00
8116.96	0.00	0.00

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SDF5338P

TOTAL LABOUR CHARGES	5242.00	3322
TOTAL SPARE PARTS CHARGES	8116.96	4975.60
GRAND TOTAL	13358.96	* TOTAL - 8297.60

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME

SURVEYED DATE

AUTHORIZED DATE

EXCESS CLAUSE

LIABILITY

REMARKS

: Rasul - 140 90010068
: 14/02/23 @ 1146
: 6 days
: 0.00
: 0.00
: Resurvey before paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: