

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23001560/KPA3Q2
Date: 18/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993555
Claimant Vehicle No :	SMN6221L	Insured Vehicle No :	SNF9678M
Date of Loss:	04/02/2023	Nature of Claim:	TP
		Claim No:	1684365945SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN6221L	Engine No:	LEB5642552
Make & Model:	HONDA FREED HYBRID, 1.5 G (A)	Chassis No:	GB71101370
Reg. Date:	20/08/2019 (Man. Year: 2019)	Odometer:	60043 km
Colour:	Metallic Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	West Lake 9 mm	Rear Left Side:	West Lake 9 mm
Front Right Side:	West Lake 9 mm	Rear Right Side:	West Lake 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,924.32	2,514.08	410.24	14.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,830.00	1,600.00	230.00	12.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,754.32	4,114.08	640.24	13.47
Approved Total (Overridden) (S\$)		3,700.00		
(S\$)	4,754.32	3,700.00	1,054.32	22.18
+ GST 8.00/8.00% (S\$)	380.35	296.00	84.35	22.18
Nett Amount (S\$)	5,134.67	3,996.00	1,138.67	22.18
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		26.75		
Nett Liability (S\$)		4,722.75		

INSPECTION

Date of Assignment:	08/02/2023		
Date Inspected:	08/02/2023	Inspected At:	Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76 Singapore 575642
Estimated Period of Repair:	6.0 days		

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	1,100.00 FL	*1,100.00 FL
2	1		*TAIL GATE GLASS MOULDING	Necessary	86.40 FL	*86.40 FL
3	1		*TAIL GATE INNER TRIM COVER	Serviceable	288.00 FL	*- FL
4	1		*TAIL GATE OPEN POCKET	Serviceable	25.00 FL	*- FL
5	1		*TAIL GATE FREED EMBLEM	Necessary	55.00 FL	*55.00 FL
6	1		*TAIL GATE HYBRID PLATE	Necessary	75.00 FL	*75.00 FL
7	1		*REAR END PANEL	Bent	423.70 FL	*423.70 FL
8	1		*END PANEL TOP GARNISH	Buckled	115.00 FL	*115.00 FL
9	1		*REAR BUMPER FASCIA	Buckled	950.00 FL	*950.00 FL
10	2		*REAR BUMPER SIDE RETAINER	Serviceable	49.80 FL	*- FL
11	1		*REAR W/S GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
12	1		*REAR BUMPER REVERSE SENSOR	Dented	300.00 FS	*200.00 FS
13	1		*REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,557.90	3,075.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	633.58	561.02
Total Parts (\$\$)	2,924.32	2,514.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & RENEW REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	150.00	120.00
2	TO REMOVE ROOF LINING ,FRONT AND REAT SEATS ,TRIM BOARD AND CARPET	New	120.00	60.00
3	TO APPLY UNDERSEALING	New	60.00	60.00
4	TO PUTTY AND SPRAY REPLACED PARTS	New	700.00	660.00
5	TO REMOVE ,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS	New	800.00	700.00
			Gross Labour Cost (\$\$)	1,830.00
				1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >