

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS6/AIS23001601/HNY3M4**Date:** 09/03/2023**REFERENCE**

Insured/Claimant:	BIS MOTORING PTE LTD	Policy No:	SP2002451400
Date of Loss:	11/02/2023	Nature of Claim:	OD
		Claim No:	202332005312

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ6701S		
Make & Model:	KIA CARENS, 1.7 D DCT DIESEL 5DR FWD (A)	Engine No:	D4FDJH551767
Reg. Date:	15/05/2018 (Man. Year: 2018)	Chassis No:	KNAHU815VJ7205603
Colour:	White	Odometer:	414635 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	S\$46,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:		Rear Tyre Size:	
Front Left Side:	6 mm	Rear Left Side:	6 mm
Front Right Side:	6 mm	Rear Right Side:	6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,346.00	1,878.80	3,467.20	64.86
Miscellaneous Items	69.00	35.00	34.00	49.28
Labour	3,190.00	1,280.00	1,910.00	59.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,605.00	3,193.80	5,411.20	62.88
- Excess (S\$)	0.00	2,000.00	-2,000.00	
(S\$)	8,605.00	1,193.80	7,411.20	86.13
+ GST 8.00/8.00% (S\$)	688.40	95.50	592.90	86.13
Nett Amount (S\$)	9,293.40	1,289.30	8,004.10	86.13

INSPECTION

Date of Assignment:	14/02/2023	Present Location:	Munich Autocare Pte Ltd (HQ)
			Munich Autocare Pte Ltd (HQ)
Date Inspected:	14/02/2023	Inspected At:	60 Jalan Lam Huat, #07-43
			Carros Center Singapore 737869
Estimated Period of Repair:	5.0 days		

Adjuster: Edward**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Mar 2023)
Parts:	M1-MPV	KIA CARENS 1.7 D DCT DIESEL 5DR FWD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ6701S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	A66400A4000	*front bonnet (WCP)	Buckled	320.00 F	*340.00 F
2	1	A86320A4000	*front bonnet logo (WCP)	Not Necessary	30.00 F	*- F
3	1	A79100A4000	*front bonnet hinge LH (WCP)	Bent	18.00 F	*18.00 F
4	1	A81130A4900	*Front bonnet lock (WCP)	Not Necessary	30.00 F	*- F
5	1	A86511A4800	*Front bumper (WCP)	Cracked	240.00 F	*250.00 F
6	1	A86350A4810	*front radiator grille (WCP)	Cracked	195.00 F	*202.00 F
7	1	A86366A4000	*front bumper top cover (WCP)	Not Necessary	35.00 F	*- F
8	1	A86585A4800	*front bumper top inner garnish (WCP)	Not Necessary	4.00 F	*- F
9	1	A86585A4800	*front headlamp LH (WCP)	Not Necessary	650.00 F	*- F
10	1	A92102A4160	*front headlamp RH (WCP)	Cracked	650.00 F	*670.00 F
11	1	A86511A4000	*front headlamp bracket LH (WCP)	Not Necessary	8.00 F	*- F
12	1	A86552A4000	*front headlamp bracket RH (WCP)	Not Necessary	8.00 F	*- F
13	1	A86513A4800	*front bumper rentainer LH (WCP)	Not Necessary	8.00 F	*- F
14	1	A86514A4800	*front bumper rentainer RH (WCP)	Not Necessary	8.00 F	*- F
15	1	A86520A4800	*front bumper sponge (WCP)	Broken	45.00 F	*45.00 F
16	1	A86530A4000	*front bumper reinforcement (WCP)	Not Necessary	160.00 F	*- F
17	1	A64101A4000	*front support panel (WCP)	Repair	250.00 F	*- F
18	1	CD00891	*front a/cond condensor (WCP)	Not Necessary	380.00 F	*- F
19	1	25310A4560	*front radiator assy (WCP)	Not Necessary	380.00 F	*- F
20	1	A25380A4510	*fan cooling fan cowing (WCP)	Not Necessary	380.00 F	*- F
21	1	A79120A4000	*Front bonnet hinge RH (WCP)	Not Necessary	18.00 F	*- F
22	2	A95720-A4100IM	*rear reverse sensor (WCP)	Not Necessary	160.00 F	*- F
23	1		*rear reverse sensor harness (WCP)	Not Necessary	90.00 F	*- F
24	1	28271-2A480	*INTER COOLER (WCP)	Not Necessary	600.00 F	*- F
Supplementary #1						
25	1	66321A4000	*FRONT FENDER RH (WCP)	Buckled	175.00 F	*165.00 F
26	1	79120A4000	*HINGLE RH (WCP)	Bent	18.00 F	*18.00 F

F=Franchise part.

Sub Total (S\$)				4,860.00	1,708.00
Report was unsubmitted during this print-out.					

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT ENGINE COOLANT Not Necessary	25.00	0.00
2	1	FRONT NUMBER PLATE WITH CASING Necessary	35.00	35.00
3	6	FRONT RADIATOR TOP GARNISH CLIPS Not Necessary	9.00	0.00
Sub Total (S\$)			69.00	35.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX, REPAIR, KNOCKING, WELDING FRONT PORTION, BONNET , BUMPER AND DAMAGE AREA	New	1,200.00	400.00
2	TO CHECK ALL WIRING FOR OPERATION AND PARKING SENSOR FOR OPERATION }	New	120.00	30.00
3	TO CHECK AND ADJUST HEADLAMP LH/RH FOCUS }	New	120.00	0.00
4	TO REMOVE/INSTALL RADIATOR COOLING SYSTEM & ALL NECESSARY PARTS, INCLUDING PRESSURE TEST, BLEED COOLING SYSTEM & CHECK LEAKS FOR REPLACE FRONT SUPPORT PANEL AND DAMAGE AREA	New	350.00	0.00
5	TO REFILL A/COND GAS	New	120.00	0.00
6	TO RESPRAY FRONT PORTION, BONNET, BUMPER, FRONT FENDER LH/RH AND DAMAGE AREA	New	800.00	450.00
Supplementary #1				
Labour Items				
7	TO RESPRAY FRONT FENDER RH	New	200.00	200.00
8	TO REMOVE, REFIX AND KNOCKING FRONT FENDER RH	New	280.00	200.00
Gross Labour Cost (S\$)			3,190.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >