

Munich Autocare Pte Ltd (Co.Reg.No:201832250M)

60 Jalan Lam Huat, #07-43

Singapore 737869

Tel: 62552288 Fax: 62655388 Email: dennis.deng@munichautocare.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SP2002451400	Date of Loss:	11/02/2023
Vehicle Reg. No.:	SLZ6701S	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	BIS MOTORING PTE LTD		
Make/Model:	KIA CARENS, 1.7 D DCT DIESEL 5DR FWD (A)	Vehicle Reg. Date:	15/05/2018
Vehicle Colour:	White		
Engine No:	D4FDJH551767	Chassis No:	KNAHU815VJ7205603
Odometer:	414635 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	9		
Present Location:	MUNICH AUTOCARE PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	5,133.70
Miscellaneous Items	69.00
Labour	2,710.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	7,912.70
+ GST 8.00% (S\$)	633.02
Nett Amount (S\$)	8,545.72

This claim is handled by: **LEONG CHEE KWONG**Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Feb 2023)

Parts: M1-MPV KIA CARENS 1.7 D DCT DIESEL 5DR FWD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Munich Autocare Pte Ltd/SLZ6701S/13/02/2023 17:04

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	A66400A4000	*front bonnet	0.00	0.00	*320.00 F
2	1	A86320A4000	*front bonnet logo	0.00	0.00	*30.00 F
3	1	A79100A4000	*front bonnet hinge LH	0.00	0.00	*18.00 F
4	1	A81130A4900	*Front bonnet lock	0.00	0.00	*30.00 F
5	1	A86511A4800	*Front bumper	0.00	0.00	*240.00 F
6	1	A86350A4810	*front radiator grille	0.00	0.00	*195.00 F
7	1	A86366A4000	*front bumper top cover	0.00	0.00	*35.00 F
8	1	A86585A4800	*front bumper top inner garnish	0.00	0.00	*4.00 F
9	1	A86585A4800	*front headlamp LH	0.00	0.00	*650.00 F
10	1	A92102A4160	*front headlamp RH	0.00	0.00	*650.00 F
11	1	A86511A4000	*front headlamp bracket LH	0.00	0.00	*8.00 F
12	1	A86552A4000	*front headlamp bracket RH	0.00	0.00	*8.00 F
13	1	A86513A4800	*front bumper rentainer LH	0.00	0.00	*8.00 F
14	1	A86514A4800	*front bumper rentainer RH	0.00	0.00	*8.00 F
15	1	A86520A4800	*front bumper sponge	0.00	0.00	*45.00 F
16	1	A86530A4000	*front bumper reinforcement	0.00	0.00	*160.00 F
17	1	A64101A4000	*front support panel	0.00	0.00	*250.00 F
18	1	CD00891	*front a/cond condensor	0.00	0.00	*380.00 F
19	1	25310A4560	*front radiator assy	0.00	0.00	*380.00 F
20	1	A25380A4510	*fan cooling fan cowing	0.00	0.00	*380.00 F
21	1	A79120A4000	*Front bonnet hinge RH	0.00	0.00	*18.00 F
22	2	A95720-A4100IM	*rear reverse sensor	0.00	0.00	*160.00 F
23	1		*rear reverse sensor harness	0.00	0.00	*90.00 F
24	1	28271-2A480	*INTER COOLER	0.00	0.00	*600.00 F

F=Franchise part.

Sub Total (\$\$)	4,667.00
+ Margin on L,N Items 10.00% (\$\$)	466.70

Total Parts (\$\$)	5,133.70
---------------------------	-----------------

Munich Autocare Pte Ltd/SLZ6701S/13/02/2023 17:04. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRONT ENGINE COOLANT	25.00
2	1	FRONT NUMBER PLATE WITH CASING	35.00
3	6	FRONT RADIATOR TOP GARNISH CLIPS	9.00
Sub Total (\$\$)			69.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REMOVE & REFIX, REPAIR, KNOCKING, WELDING FRONT PORTION, BONNET , BUMPER AND DAMAGE AREA	New	1,200.00
2	TO CHECK ALL WIRING FOR OPERATION AND PARKING SENSOR FOR OPERATION	New	120.00
3	TO CHECK AND ADJUST HEADLAMP LH/RH FOCUS	New	120.00
4	TO REMOVE/INSTALL RADIATOR COOLING SYSTEM & ALL NECESSARY PARTS, INCLUDING PRESSURE TEST, BLEED COOLING SYSTEM & CHECK LEAKS FOR REPLACE FRONT SUPPORT PANEL AND DAMAGE AREA	New	350.00
5	TO REFILL A/COND GAS	New	120.00
6	TO RESPRAY FRONT PORTION, BONNET, BUMPER, FRONT FENDER LH/RH AND DAMAGE AREA	New	800.00
Gross Labour Cost (\$\$)			2,710.00

Munich Autocare Pte Ltd/SLZ6701S/13/02/2023 17:04. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >