

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 15 Feb 2023

Preliminary Advice

Vehicle No	: SLZ6701S	Accident Date	: 11/02/2023
Make	: KIA CARENS	Policy No.	: SP2002451400
Assignment Date	: 14/02/2023	Excess	: S\$2,000.00
Date of Inspection	: 14/02/2023	Est. Duration of Repair	: 5
Inspection At	: MUNICH AUTOCARE PTE LTD (HQ) 60 JALAN LAM HUAT, #07-43 SINGAPORE 737869		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,912.70
Revised Amount	:S\$	1,499.10
Check Items (Estimated)	:S\$	4,170.40
Total	:S\$	5,669.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	46,000.00
COE / PARF Rebate	:S\$	36,211.00
Salvage Value	:S\$	
Margin for Repair	:S\$	9,789.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :*the vehicle repair on part by parts basis.due to no second parts available.*
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.