

(08/11/13)

REF

CSG/AIS23001601/HAY3

ASS. REC. BY:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: 2000

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 46,000

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLZ 67015 Yr Regn: 15/5/2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or PRIVATE HIRE

Make: KIA CARENS, 1.7D c.c 1685

Colour: WHITE. A/C: Insured / Std / NI / NA

Sp. Reading: 414635 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAHU815VJ7205603

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NIL / S/Rlm / STD A/Rlm or

Tyre Size: F: NO PHOTO

R: NO PHOTO

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or NO PHOTO

Front

Rear

R/Bal. - mm R/Bal. - mm

L/Bal. - mm L/Bal. - mm

D.O.A. 11/2/2023

D.O.I.

Survey held at DESKTOP LKDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Edward confirmed. final fig \$ 3193.80 and 5 days
	(Red, \$ 5411.20, 63%)

Date/Time, File Pass to?

☐ : Prell. Report

1) 1/3/23

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 5

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format: OD

Lump Sum / I.B.I: (\$ 3193.80)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	055D
Vehicle Details	
Vehicle No.:	SLZ6701S
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Feb 2023
Vehicle Make:	KIA
Vehicle Model:	CARENS 1.7 DCT DIESEL 5DR FWD
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	D4FDJH551767
Chassis No.:	KNAHU815VJ7205603
Maximum Power Output:	104.0 kW (139 bhp)
Open Market Value:	\$21,399.00
Original Registration Date:	15 May 2018
First Registration Date:	15 May 2018
Transfer Count:	0
Actual ARF Paid:	\$21,959.00 x 50% = 10,979
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 May 2028
PARF Rebate Amount:	\$16,469.00
Intended COE Rebate Details	
COE Expiry Date:	14 May 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$38,039.00
COE Rebate Amount:	\$19,742.00
Total Rebate Amount:	\$36,211.00

The information contained herein is correct as at 14 Feb 2023

OK

5 years 3 mth 4 days
63 mth 4 days
1920 days.

$$\text{Market Value} = \frac{13560}{365} \times 1920 + 10,979$$

$$= 82,308$$

$$\text{Rebate} = 36,211$$

$$\text{Net Value} = 46,097 \Rightarrow 46,000$$

Munich Autocare Pte Ltd (Co.Reg.No:201832250M)

60 Jalan Lam Huat, #07-43

Singapore 737869

Tel: 62552288 Fax: 62655388 Email: dennis.deng@munichautocare.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SP2002451400	Date of Loss:	11/02/2023
Vehicle Reg. No.:	SLZ6701S	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	BIS MOTORING PTE LTD		
Make/Model:	KIA CARENS, 1.7 D DCT DIESEL 5DR FWD (A)	Vehicle Reg. Date:	15/05/2018
Vehicle Colour:	White		
Engine No:	D4FDJH551767	Chassis No:	KNAHU815VJ7205603
Odometer:	414635 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	9.5		
Present Location:	MUNICH AUTOCARE PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	5,133.70
Miscellaneous Items	69.00
Labour	2,710.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	7,912.70
+ GST 8.00% (S\$)	633.02
Nett Amount (S\$)	8,545.72

This claim is handled by: **LEONG CHEE KWONG**Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Feb 2023)

Parts: M1-MPV KIA CARENS 1.7 D DCT DIESEL 5DR FWD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Munich Autocare Pte Ltd/SLZ6701S/13/02/2023 17:04

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1	A66400A4000	*front bonnet	0.00	0.00	340 *320.00 F	BUC
2	1	A86320A4000	*front bonnet logo	0.00	0.00	*30.00 F	X NN
3	1	A79100A4000	*front bonnet hinge LH	0.00	0.00	18 *18.00 F	X BT
4	1	A81130A4900	*Front bonnet lock	0.00	0.00	*30.00 F	X NN
5	1	A86511A4800	*Front bumper	0.00	0.00	250 *240.00 F	X CRA
6	1	A86350A4810	*front radiator grille	0.00	0.00	202 *195.00 F	X CRA
7	1	A86366A4000	*front bumper top cover	0.00	0.00	*35.00 F	X NN
8	1	A86585A4800	*front bumper top inner garnish	0.00	0.00	*4.00 F	X NN
9	1	A86585A4800	*front headlamp LH	0.00	0.00	*650.00 F	X NN
10	1	A92102A4160	*front headlamp RH	0.00	0.00	670 *650.00 F	X CRA
11	1	A86511A4000	*front headlamp bracket LH	0.00	0.00	*8.00 F	X NN
12	1	A86552A4000	*front headlamp bracket RH	0.00	0.00	*8.00 F	X NN
13	1	A86513A4800	*front bumper rentainer LH	0.00	0.00	*8.00 F	X NN
14	1	A86514A4800	*front bumper rentainer RH	0.00	0.00	*8.00 F	X NN
15	1	A86520A4800	*front bumper sponge	0.00	0.00	45 *45.00 F	X BR
16	1	A86530A4000	*front bumper reinforcement	0.00	0.00	*160.00 F	X NN
17	1	A64101A4000	*front support panel	0.00	0.00	*250.00 F	X R
18	1	CD00891	*front a/cond condensor	0.00	0.00	*380.00 F	X NN
19	1	25310A4560	*front radiator assy	0.00	0.00	*380.00 F	X NN
20	1	A25380A4510	*fan cooling fan coving	0.00	0.00	*380.00 F	X NN
21	1	A79120A4000	*Front bonnet hinge RH	0.00	0.00	*18.00 F	X NN
22	2	A95720-A4100IM	*rear reverse sensor	0.00	0.00	*160.00 F	X NN
23	1		*rear reverse sensor harness	0.00	0.00	*90.00 F	X NN
24	1	28271-2A480	*INTER COOLER	0.00	0.00	*600.00 F	X NN

F=Franchise part.

Sub Total (S\$)	4,667.00
+ Margin on L,N Items 10.00% (S\$)	466.70
Total Parts (S\$)	5,133.70

Munich Autocare Pte Ltd/SLZ6701S/13/02/2023 17:04. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

24/2/2023

- Parts by Parts.
- Provide old bumper, bonnet, grille in front of car photo
- Cross out ? items.

1700

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT ENGINE COOLANT	25.00 XNN
2	1	FRONT NUMBER PLATE WITH CASING	35.00 XNEC
3	6	FRONT RADIATOR TOP GARNISH CLIPS	9.00 XNN
Sub Total (S\$)			69.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REMOVE & REFIX, REPAIR, KNOCKING, WELDING FRONT PORTION, BONNET , BUMPER AND DAMAGE AREA	New	1,200.00 400
2	TO CHECK ALL WIRING FOR OPERATION AND PARKING SENSOR FOR OPERATION	New	120.00 330
3	TO CHECK AND ADJUST HEADLAMP LH/RH FOCUS	New	120.00
4	TO REMOVE/INSTALL RADIATOR COOLING SYSTEM & ALL NECESSARY PARTS, INCLUDING PRESSURE TEST, BLEED COOLING SYSTEM & CHECK LEAKS FOR REPLACE FRONT SUPPORT PANEL AND DAMAGE AREA	New	350.00 XNN
5	TO REFILL A/COND GAS	New	120.00 XNN
6	TO RESPRAY FRONT PORTION, BONNET, BUMPER, FRONT FENDER LH/RH AND DAMAGE AREA	New	800.00 450
Gross Labour Cost (S\$)			2,710.00

Munich Autocare Pte Ltd/SLZ6701S/13/02/2023 17:04. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

- Not Authorise

- Excess = \$2000/2

- P/P or L/S repair.

- Survey by EDWARD LAY

contact number. : 62563561

- Resurvey before paint for P/P repair.

Premier Automotive Services Pte Ltd (Co.Reg.No:201832250M)

60 Jalan Lam Huat Carros Centre, #07-43

Singapore 737869

Tel: 62552288 Fax: 62655388 Email: dennis.deng@munichautocare.com.sg

(SUPPLEMENTARY)INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type: OD (OWN DAMAGE)
 Policy No: SP2002451400
 Vehicle Reg. No.: **SLZ6701S**
 Driver Age/Info:
 TP Injury Involved? YES
 Insured/Claimant: BIS MOTORING PTE LTD

Ref. No:
 Date of Loss: 11/02/2023
 Driveable?
 Party At Fault: UNKNOWN
 Third Party Involved? YES

Make/Model: KIA CARENS, 1.7 D DCT DIESEL
 5DR FWD (A)
 Vehicle Colour: WHITE
 Engine No: D4FDJH551767
 Odometer: 414635 KM

Vehicle Reg. Date: 15/05/2018

Chassis No: KNAHU815VJ7205603

Paint Type:
 Total Loss? **NO**
 Est. Duration of Repair (day) **9** *5*

Present Location: **MUNICH AUTOCARE PTE LTD (HQ)****COST OF CLAIMS**

	Amount
Parts	212.30
Miscellaneous Items	0.00
Labour	<i>400</i> 480.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (S\$) 692.30**+ GST 8.00% (S\$) 55.38****Nett Amount (S\$) 747.68****+ Previous Estimates (S\$) 8,545.72****Claim Total (S\$) 9,293.40**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Feb 2023)

Parts: M1-MPV KIA CARENS 1.7 D DCT DIESEL 5DR FWD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Premier Automotive Services Pte Ltd/SLZ6701S/20/02/2023 16:41

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	66321A4000	*FRONT FENDER RH	0.00	0.00	165 *175.00 F
2	1	79120A4000	*HINGLE RH	0.00	0.00	18 *18.00 FBT
F=Franchise part.						
Sub Total (S\$)						193.00
+ Margin on L,N Items 10.00% (S\$)						19.30
Total Parts (S\$)						212.30

Premier Automotive Services Pte Ltd/SLZ6701S/20/02/2023 16:41. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO RESPRAY FRONT FENDER RH	New	200.00
2	TO REMOVE, REFIX AND KNOCKING FRONT FENDER RH	New	280.00 200
Gross Labour Cost (\$)			480.00

Premier Automotive Services Pte Ltd/SLZ6701S/20/02/2023 16:41. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >