

Premier Automotive Services Pte Ltd (Co.Reg.No:201832250M)

60 Jalan Lam Huat Carros Centre, #07-43

Singapore 737869

Tel: 62552288 Fax: 62655388 Email: dennis.deng@munichautocare.com.sg

(SUPPLEMENTARY)**INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2002451400	Date of Loss:	11/02/2023
Vehicle Reg. No.:	SLZ6701S	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	BIS MOTORING PTE LTD		
Make/Model:	KIA CARENS, 1.7 D DCT DIESEL 5DR FWD (A)	Vehicle Reg. Date:	15/05/2018
Vehicle Colour:	WHITE		
Engine No:	D4FDJH551767	Chassis No:	KNAHU815VJ7205603
Odometer:	414635 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	9		
Present Location:	MUNICH AUTOCARE PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	212.30
Miscellaneous Items	0.00
Labour	480.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	692.30
+ GST 8.00% (\$\$)	55.38
Nett Amount (\$\$)	747.68
+ Previous Estimates (\$\$)	8,545.72
Claim Total (\$\$)	9,293.40

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 20 Feb 2023)**Parts:** M1-MPV KIA CARENS 1.7 D DCT DIESEL 5DR FWD (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Premier Automotive Services Pte Ltd/SLZ6701S/20/02/2023 16:41**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	66321A4000	*FRONT FENDER RH	0.00	0.00	*175.00 F
2	1	79120A4000	*HINGLE RH	0.00	0.00	*18.00 F
						Sub Total (\$)
						193.00
						+ Margin on L,N Items 10.00% (\$)
						19.30
						Total Parts (\$)
						212.30

F=Franchise part.

Premier Automotive Services Pte Ltd/SLZ6701S/20/02/2023 16:41. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO RESPRAY FRONT FENDER RH	New	200.00
2	TO REMOVE, REFIX AND KNOCKING FRONT FENDER RH	New	280.00
Gross Labour Cost (S\$)			480.00

Premier Automotive Services Pte Ltd/SLZ6701S/20/02/2023 16:41. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >