

ASS. REC. BY:

REF:

AG2/23001616/KK Kqy3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1) 15/03/23 GIA not ready

Kenneth confirmed lump sum: \$3250 and 5 days
(red, \$5232.76, 62%)

Veh No:

GBG 5942 Mr Regn: 09, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS NV200 c.c. 1461

Colour

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

202329

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VSKYBAM2070146885

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / Std Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

13/2/23

D.O.I.

14/2/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1) 15/03/23

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$

☐ : Prel. Report

☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee:

Add Fee:

☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech Invs (\$)

☐ : Weekend (\$)

Transportation

S - RS - SI

Fees

Others

TOTAL

EM Solution Pte Ltd

160 Sin Ming Drive #03-18/19, Sin Ming Autocity

Singapore 575722

Tel: 64560226 Fax: 64584500

GST Reg. No: 201016308K

*Not Authorized
11 May &
Repair After Paint
5 days*

ESTIMATE

Date :

M/s **G H Ong Engineering Pte Ltd**
31 Bukit Batok Crescent, #01-50
Singapore 658070

Veh No : **GBG 5942M**
Make/Model : **Nissan NV200**
Chassis No : VSKYBAM20Z0146885
Date of Acc : 13.02.23
TP Veh No : SLP 1867H

S/No	Qty	Description	Unit Price	Amount
Materials (Nett)				
1	1 pc	Rear Tailgate RH <i>By ✓</i>		
2	1 pc	Rear Tailgate Mechanism Lock, Lower RH <i>7</i>		
3	1 pc	Rear Tailgate Hinge, Lower RH <i>By ✓</i>		
4	1 pc	Rear Tailgate Center Checker RH <i>7</i>		
5	1 pc	Rear Tailgate Inner Board RH <i>Pin X</i>		
6	1 pc	Rear Bumper <i>Bulma</i>		
7	2 pcs	Rear Bumper Bracket L/R		
8	1 pc	Rear Bumper Inner Sponge <i>Pin X</i>		
9	1 pc	Rear Bumper Tow Cover <i>Pin X</i>		
10	1 pc	Rear Bumper Reflector RH <i>Pin X</i>		
11	1 pc	Rear Lamp RH <i>CPM</i>		
12	1 pc	Rear Body Panel RH <i>RY</i>		
13	1 pc	Rear End Panel <i>7</i>		
14	1 pc	Rear End Panel Top Garnish <i>7</i>		
15	1 pc	Rear Boot Weatherstrip <i>original 501m</i>		

	\$	-
Less 10%	\$	-
Parts Total :	\$	-

Special Nett		
1	1 set	Reverse Sensor
2	1 set	Rear Bumper Clips
3	1 set	End Panel Top Garnish Clips
4	1 set	Rear Tailgate Inner Board Clips
5	1 pc	Windscreen Sealant
6	1 set	RH Body Co's Sticker

<i>RM</i>	280.00	<i>2001m</i>
<i>\$</i>	45.00	
<i>\$</i>	35.00	<i>7</i>
<i>\$</i>	35.00	<i>X</i>
<i>\$</i>	50.00	<i>401m</i>
<i>nn</i>	400.00	<i>X</i>
Special Nett :	\$	845.00

Labour		
1	To remove & rearrange electrical wirings, check lightings	
2	To remove & replace upholstery, floor board & trim garnishes. (to facilitate repairs)	
3	To remove, instal rear tailgate glass RH.	
4	To remove, transfer tailgate components.	
5	To remove, repair & replace damaged bodyparts, realign bodywork and where consistent to the accident.	
6	Putty and respray painting on affected portions.	
7	To remove & renew reverse sensor	
8	Rust proofing on affected portions.	

\$	80.00	<i>201</i>
\$	100.00	<i>601</i>
\$	100.00	<i>601</i>
\$	100.00	<i>601</i>
\$	1,000.00	<i>7</i>
\$	1,000.00	<i>6001</i>
\$	150.00	<i>501</i>
\$	80.00	<i>301</i>
Labour Total :	\$	2,610.00
Total Parts & Labour :		

for EM Solution Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Note: Parts quoted were based on visual inspection. Should additional parts be found damaged upon dismantling, we will seek your approval before proceeding.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

632C

Owner ID:

Vehicle Details

Vehicle No.:

GBG5942M

Vehicle to be Exported:

No

Intended Deregistration Date:

14 Feb 2023

Vehicle Make:

NISSAN

Vehicle Model:

NV200 1.5 MT ABS AIRBAG 2WD 6DR E5 W/RC

Primary Colour:

Silver

Manufacturing Year:

2017

Engine No.:

K9KC400D057567

Chassis No.:

VSKYBAM20Z0146885

Maximum Power Output:

-

Open Market Value:

\$20,119.00

Original Registration Date:

07 Sep 2017

First Registration Date:

07 Sep 2017

Transfer Count:

0

Actual ARF Paid:

\$1,006.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

06 Sep 2027

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

QP Paid:

\$42,809.00

COE Rebate Amount:

\$19,531.00

Total Rebate Amount:

\$19,531.00

The information contained herein is correct as at 13 Feb 2023

OK