

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: JANICE KOH

Date: 15 Feb 2023

**Preliminary Advice**

Vehicle No	: SLN8972B	Accident Date	: 26/01/2023
Make	: MERCEDES-BENZ A180	Policy No.	: SP2003907937
Assignment Date	: 14/02/2023	Excess	: S\$700.00
Date of Inspection	: 14/02/2023	Est. Duration of Repair	: 4
Inspection At	: TONG LUCK AUTO PTE LTD (HQ) 160 SIN MING DRIVE, #07-01 SIN MING AUTOCITY SINGAPORE 575722		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,233.80
Revised Amount	:S\$	3,744.40
Check Items (Estimated)	:S\$	1,189.40
Total	:S\$	4,933.80

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	73,000.00
COE / PARF Rebate	:S\$	34,390.00
Salvage Value	:S\$	
Margin for Repair	:S\$	38,610.00

**Remarks**

- ( x ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments :*the vehicle repair on part by parts basis.due to no second parts available.*  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.