



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Website: www.tlauto.com.sg

Email : operation@tlauto.com.sg

UEN: 201700521W GST NO.: 201700521W

TAX INVOICE

M/S : ALLIANZ INSURANCE SINGAPORE PTE LTD

79, ROBINSON ROAD #09-01
SINGAPORE 068897

TEL : 67143369

FAX :

ATTN: MOTOR CLAIMS DEPT

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 26/01/2023

NO : AR202305-0018

CLAIM NO : QUOT202302-000026(01)

DATE : 11/05/2023

POLICY NO : SP2003907937

VEH REG : SLN8972B

MAKE/MODEL : MERCEDES BENZ A180 FL
STYLE (R17 HLG)

CHASIS NO : WDD1760422J584823

ENGINE NO : 27091031239675

REG. DATE : 2017

Final Repair Cost to Vehicle No : SLN8972B

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Headlamp assy LH	1	620.00	620.00
2 Front fender LH	1	490.00	490.00
3 Front bumper	1	780.00	780.00
4 Front bumper side retainer LH	1	24.00	24.00
5 Front bumper sensor seals	6	8.00	48.00
6 Front sport rim LH	1	690.00	690.00
			2,652.00
		Add 10%	265.20
			2,917.20
SPECIAL NET			
7 Front fender inner shield clips - LH (set)	1	50.00	50.00
8 Front bumper clips (set)	1	50.00	50.00
			100.00
LABOUR			
10 To remove and refit front bumper sensor	1	60.00	60.00
11 To check and rectify wiring system	1	20.00	20.00
12 To panel beat and straighten front support panel, LH front fender inner panel, LH front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	400.00	400.00
13 To putty and spray paint on the affected areas	1	400.00	400.00
14 To reset and reprogram headlamp fault code	1	250.00	250.00
15 To computerise check wheel alignment	1	60.00	60.00
			1,190.00



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Website: www.tlauto.com.sg

Email : operation@tlauto.com.sg

UEN: 201700521W GST NO.: 201700521W

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD

79, ROBINSON ROAD #09-01
SINGAPORE 068897

TEL : 67143369

FAX :

ATTN: MOTOR CLAIMS DEPT

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 26/01/2023

TAX INVOICE

NO : AR202305-0018

CLAIM NO : QUOT202302-000026(01)

DATE : 11/05/2023

POLICY NO : SP2003907937

VEH REG : SLN8972B

MAKE/MODEL : MERCEDES BENZ A180 FL
STYLE (R17 HLG)

CHASIS NO : WDD1760422J584823

ENGINE NO : 27091031239675

REG. DATE : 2017

Final Repair Cost to Vehicle No : SLN8972B

Description	Quantity	Unit Price	Amount
		<u>S\$</u>	<u>S\$</u>
		AMOUNT:	S\$ 4,207.20
		LESS EXCESS:	S\$ 700.00
		TOTAL:	S\$ 3,507.20
		ADD GST @ 8%:	S\$ 280.58
		GRAND TOTAL:	<u><u>S\$ 3,787.78</u></u>

SINGAPORE DOLLARS THREE THOUSAND SEVEN HUNDRED AND EIGHTY-SEVEN AND CENTS SEVENTY-EIGHT ONLY

TONG LUCK AUTO PTE LTD

E. & O.E.

AUTHORISED SIGNATURE