



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

SUNeYed by Kenneth LICK on

PAGE: 1

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD

79, ROBINSON ROAD #09-01
SINGAPORE 068897

ESTIMATE

14/2/2023 @ 11:30am

NO : QUOT202302-000026(00)

DATE : 07/02/2023

POLICY NO : SP2003907937

VEH REG NO : SLN8972B

MAKE/MODEL : MERCEDES BENZ A180 FL
STYLE (R17 HLG)

CHASSIS NO : WDD1760422J584823

ENGINE NO : 27091031239675

REG. DATE : 2017

ATTN : MOTOR CLAIMS DEPT

TEL : FAX :

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 26/01/2023

Estimate Repair Cost to Vehicle No : SLN8972B

Description	Quantity	Unit Price	Amount
		SS	SS
PARTS			
1 Headlamp assy LH	1	620.00	620.00 ✓
2 Front fender LH	1	490.00	490.00 ✓
3 Front fender inner shield LH	1	168.00	168.00 X
4 Front bumper	1	780.00	780.00 ✓
5 Front bumper side retainer LH	1	24.00	24.00 ✓
6 Front bumper sensor LH	1	138.00	138.00 X
7 Front bumper sensor seals necessary	6	8.00	48.00 X ✓
8 Front sport rim LH	1	690.00	690.00 ✓
Front bumper clips \$50/- SN			2,958.00
Front fender inner shield clips \$50/- SN			3,253.80
SPECIAL NET			
9 Front tyre LH	1	450.00	450.00 X
LABOUR			
10 To remove and refit front bumper sensor	1	100.00	100.00 60/-
11 To check and rectify wiring system	1	80.00	80.00 20/-
12 To panel beat and straighten front support panel, LH front fender inner panel, LH front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00 400/-
13 To putty and spray paint on the affected areas	1	1,000.00	1,000.00 400/-
14 To reset and reprogram headlamp fault code	1	350.00	350.00 70/-
To computerise check wheel alignment			2,530.00
TOTAL			SS 6,233.80
ADD GST @ 8%			498.70
GRAND TOTAL			SS 6,732.50

SINGAPORE DOLLAR SIX THOUSAND SEVEN HUNDRED THIRTY-TWO AND CENTS FIFTY ONLY

Resurvey on 20/2/2023 @ 10:05am - 4207.20

(Before paint)

XS 4,247.20
700.00

8% 3,547.20
283.78

3,830.98

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

To submit Supplement for approval