



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : ALLIANZ INSURANCE SINGAPORE PTE TLD

79, ROBINSON ROAD #09-01
SINGAPORE 068897

ESTIMATE

NO : QUOT202302-000026(00)

DATE : 07/02/2023

POLICY NO : SP2003907937

VEH REG NO : SLN8972B

MAKE/MODEL : MERCEDES BENZ A180 FL
STYLE (R17 HLG)

CHASSIS NO : WDD1760422J584823

ENGINE NO : 27091031239675

REG. DATE : 2017

ATTN : MOTOR CLAIMS DEPT

TEL : FAX :

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 26/01/2023

Not Authorised
Penang Blegam
Yday
EX TRA

Estimate Repair Cost to Vehicle No : SLN8972B

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Headlamp assy LH	1	620.00	620.00 ✓
2 Front fender LH	1	490.00	490.00 ✓
3 Front fender inner shield LH	1	168.00	168.00 ?
4 Front bumper	1	780.00	780.00 ✓
5 Front bumper side retainer LH	1	24.00	24.00 ✓
6 Front bumper sensor LH	1	138.00	138.00 ?
7 Front bumper sensor seals	6	8.00	48.00 ?
8 Front sport rim LH	1	690.00	690.00 ✓
			2,958.00
		Add 10%	295.80
			3,253.80
SPECIAL NET			
9 Front tyre LH	1	450.00	450.00 ?
			450.00
LABOUR			
10 To remove and refit front bumper sensor	1	100.00	100.00 60L
11 To check and rectify wiring system	1	80.00	80.00 20L
12 To panel beat and straighten front support panel, LH front fender inner panel, LH front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00 400L
13 To putty and spray paint on the affected areas	1	1,000.00	1,000.00 400L
14 To reset and reprogram headlamp fault code	1	350.00	350.00 ?
			2,530.00

TOTAL S\$ 6,233.80

ADD GST @ 8% 498.70

GRAND TOTAL S\$ 6,732.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTHORISED SIGNATURE

SINGAPORE DOLLAR SIX THOUSAND SEVEN HUNDRED THIRTY TWO AND CENTS FIFTY ONLY

TONG LUCK AUTO PTE LTD