

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23001623/ANP3Q2**Date:** 28/04/2023**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSNA00023222202

**Claimant Vehicle
No :** SLF9795G**Insured Vehicle
No :** SMR1270G

Date of Loss: 11/02/2023

Nature of Claim: TP

Claim
No: SNM23D201118/C02/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLF9795G**

Make & Model: HONDA VEZEL, 1.5 (A)

Engine No: L15B4024653

Reg. Date: 16/09/2016 (Man. Year: 2015)

Chassis No: RU11104651

Colour: Black

Odometer: 65647 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,753.76	6,875.60	3,878.16	36.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,050.00	2,020.00	2,030.00	50.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,803.76	8,895.60	5,908.16	39.91
Approved Total (Overridden) (\$\$)		7,100.00		
(\$\$)	14,803.76	7,100.00	7,703.76	52.04
+ GST 8.00/8.00% (\$\$)	1,184.30	568.00	616.30	52.04
Nett Amount (\$\$)	15,988.06	7,668.00	8,320.06	52.04

INSPECTION

Date of Assignment: 14/02/2023

Date Inspected: 14/02/2023 Inspected At:

Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Apr 2023)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF9795G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	845.20 FL	*845.20 FL
2	1		*FRONT BUMPER SIDE HOLDER -RH	Damaged	32.40 FL	*32.40 FL
3	1		*FRONT BUMPER TOW COVER	Deformed	30.50 FL	*30.50 FL
4	1		*FRONT BUMPER REINFORCEMENT	Dented	321.70 FL	*321.70 FL
5	1		*FRONT BUMPER LOWER SPOILER	Deformed	351.80 FL	*351.80 FL
6	1		*FRONT BUMPER FOG LAMP -RH	Not Necessary	285.40 FL	*- FL
7	1		*FRONT BUMPER FOG LAMP COVER -RH	Deformed	78.50 FL	*78.50 FL
8	1		*FRONT BUMPER LOWER RUBBER	Not Necessary	169.40 FL	*- FL
9	1		*FRONT BUMPER UNDERCOVER	Not Necessary	298.40 FL	*- FL
10	1		*FRONT GRILLE	Cracked	374.20 FL	*374.20 FL
11	1		*FRONT GRILLE BASE	Cracked	289.50 FL	*289.50 FL
12	1		*FRONT GRILLE CHROME MOULDING	Cut	342.20 FL	*342.20 FL
13	1		*FRONT GRILLE INNER BRACKET	Cracked	98.50 FL	*98.50 FL
14	1		*FRONT GRILLE LOGO	Necessary	34.60 FL	*34.60 FL
15	2		*HEADLAMP -LH & RH	Cracked	3,718.80 FL	*3,718.80 FL
16	2		*HEADLAMP LOWER BRACKET-LH & RH	Cracked	84.40 FL	*84.40 FL
17	1		*FRONT FENDER -RH	Distorted	589.40 FL	*589.40 FL
18	1		*FRONT FENDER INNER SHIELD-RH	Torn	168.40 FL	*168.40 FL
19	1		*FRONT FENDER INNER FRAME-RH	Buckled	486.70 FL	*486.70 FL
20	1		*FRONT FENDER ARC GARNISH -RH	Distorted	170.40 FL	*170.40 FL
21	1		*WIPER WASHER TANK	Deformed	166.50 FL	*166.50 FL
22	1		*WIPER WASHER TANK MOTOR	Not Necessary	58.60 FL	*- FL
23	1		*FRONT LOWER ARM -RH	Not Necessary	399.40 FL	*- FL
24	1		*FRONT SHOCK ABSORBER-RH	Not Necessary	430.10 FL	*- FL
25	1		*FRONT KNUCKLE ARM -RH	Not Necessary	461.70 FL	*- FL
26	1		*FRONT WHEEL HUB C/W BEATING -RH	Not Necessary	262.40 FL	*- FL
27	1		*ENGINE MOUNTING -RH	Damaged	285.80 FL	*285.80 FL
28	1		*FRONT SUPPORT PANEL	Repair	796.40 FL	*- FL
29	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	185.90 FL	*- FL
30	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
31	1		*SET FRONT BUMPER UNDERCOVER CLIPS	Not Necessary	30.00 FS	*- FS
32	1		*SET FRONT GRILLE CLIPS	Necessary	20.00 FS	*20.00 FS
33	1		*SET FRONT FENDER INNER SHIELD CLIPS -RH	Necessary	30.00 FS	*30.00 FS
34	1		*SET FRONT FENDER ARC GARNISH CLIPS -RH	Necessary	20.00 FS	*20.00 FS
35	1		*FRONT WHEEL RIM -RH	Not Necessary	850.00 FS	*- FS
36	1		*FRONT TYRE -RH	Not Necessary	300.00 FS	*- FS
37	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	20.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	13,117.20	8,569.50
- List Item Discount on L Items 20.00/20.00% (S\$)	2,363.44	1,693.90
Total Parts (S\$)	10,753.76	6,875.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING OUT FRONT PORTION & RENEW ABOVE PARTS	New	1,600.00	900.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	1,200.00	800.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO APPLY TUFF COAT	New	150.00	80.00
5	TO REMOVE CONDENSER & TOP-UP AIRCON GAS	New	120.00	0.00
6	TO REMOVE RADIATOR & TOP -UP COOLANT	New	120.00	0.00
7	TO DISMSNTLE FRONT UNDERCARRIAGE	New	350.00	0.00
8	TO PERFORM WHEEL ALIGNMENT	New	150.00	0.00
9	TO REPLACE ENGINE MOUNTING	New	250.00	150.00
10	TOWING FEES	New	60.00	60.00
Gross Labour Cost (S\$)			4,050.00	2,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >