

**MODERN AUTOMOTIVE PTE LTD**  
**BLK 3023A UBI ROAD 1 # 01-61**  
**SINGAPORE 408717**

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

**CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD**

3 Anson Road #16-00  
 Springleaf Tower  
 Singapore 079909  
 Tel : 6389 - 6111  
 Fax : 6224 - 7478 / 7175

*xiao Chan*

**Quotation**  
 DATE : 14.02.2023  
 VEH NO : SLF9795G  
 MODEL : Honda Vezel  
 D O A : 11.02.2023  
 YR REF : SMR1270G

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

**RE : ESTIMATE FOR ACCIDENT REPAIR SLF9795G (HONDA VEZEL)**

| <u>Item</u> | <u>Description</u>                              | <u>Qty</u> | <u>Amt</u> |
|-------------|-------------------------------------------------|------------|------------|
| <b>NO</b>   | <b>LIST ITEMS</b>                               |            |            |
| 1           | Front Bumper <i>Distorted</i>                   | 1          | 845.20 ✓   |
| 2           | Front Bumper Side Holder - RH <i>Dmgd</i>       | 1          | 32.40 ✓    |
| 3           | Front Bumper Tow Cover <i>Dehd</i>              | 1          | 30.50 ✓    |
| 4           | Front Bumper Reinforcement <i>Dented</i>        | 1          | 321.70 ✓   |
| 5           | Front Bumper Lower Spoiler <i>Dehd</i>          | 1          | 351.80 ✓   |
| 6           | Front Bumper Fog Lamp - RH <i>new</i>           | 1          | 285.40 x.  |
| 7           | Front Bumper Fog Lamp Cover - RH <i>Dehd</i>    | 1          | 78.50 ✓    |
| 8           | Front Bumper Lower Rubber <i>new</i>            | 1          | 169.40 x   |
| 9           | Front Bumper Undercover                         | 1          | 298.40 x.  |
| 10          | Front Grille <i>cracked</i>                     | 1          | 374.20 ✓   |
| 11          | Front Grille Base                               | 1          | 289.50 ✓   |
| 12          | Front Grille Chrome Moulding <i>ut</i>          | 1          | 342.20 ✓   |
| 13          | Front Grille Inner Bracket <i>cracked</i>       | 1          | 98.50 ✓    |
| 14          | Front Grille Logo <i>new</i>                    | 1          | 34.60 ✓    |
| 15          | Headlamp - LH & RH <i>cracked</i>               | 2          | 3,718.80 ✓ |
| 16          | Headlamp Lower Bracket - LH & RH <i>cracked</i> | 2          | 84.40 ✓    |
| 17          | Front Fender - RH <i>Distorted</i>              | 1          | 589.40 ✓   |
| 18          | Front Fender Inner Shield - RH <i>torn</i>      | 1          | 168.40 ✓   |
| 19          | Front Fender Inner Frame - RH <i>Buckled</i>    | 1          | 486.70 ✓   |
| 20          | Front Fender Arc Garnish - RH <i>Distorted</i>  | 1          | 170.40 ✓   |
| 21          | Wiper Washer Tank <i>Dehd</i>                   | 1          | 166.50 ✓   |
| 22          | Wiper Washer Tank Motor <i>new</i>              | 1          | 58.60 x.   |
| 23          | Front Lower Arm - RH                            | 1          | 399.40 x   |
| 24          | Front Shock Absorber - RH                       | 1          | 430.10 x   |
| 25          | Front Knuckle Arm - RH                          | 1          | 461.70 x   |
| 26          | Front Wheel Hub c/w Bearing - RH                | 1          | 262.40 x   |
| 27          | Engine Mounting - RH <i>Dmgd</i>                | 1          | 285.80 ✓   |
| 28          | Front Support Panel <i>Repair</i>               | 1          | 796.40 x.  |

**RE : ESTIMATE FOR ACCIDENT REPAIR SLF9795G (HONDA VEZEL)**

|    |                                            |                |                 |
|----|--------------------------------------------|----------------|-----------------|
| 29 | Front Support Panel Top Garnish <i>new</i> | 1              | 185.90 <i>x</i> |
|    |                                            | <i>8469.50</i> | \$ 11,817.20    |
|    | Less 20%                                   |                | (2,363.44)      |
|    |                                            | <i>6775.60</i> | \$ 9,453.76     |

**S/NETT ITEMS**

|   |                                                  |                  |                 |
|---|--------------------------------------------------|------------------|-----------------|
| 1 | Front Bumper Clips <i>new</i>                    | 1 set            | 30.00 <i>x</i>  |
| 2 | Front Bumper Undercover Clips <i>new</i>         | 1 set            | 30.00 <i>x</i>  |
| 3 | Front Grille Clips <i>new</i>                    | 1 set            | 20.00 <i>x</i>  |
| 4 | Front Fender Inner Shield Clips - RH <i>new</i>  | 1 set            | 30.00 <i>x</i>  |
| 5 | Front Fender Arc Garnish Clips - RH <i>new</i>   | 1 set <i>100</i> | 20.00 <i>x</i>  |
| 6 | Front Wheel Rim - RH <i>3 new</i>                | 1                | 850.00 <i>x</i> |
| 7 | Front Tyre - RH <i>new</i>                       | 1                | 300.00 <i>x</i> |
| 8 | Front Support Panel Top Garnish Clips <i>new</i> | 1 set            | 20.00 <i>x</i>  |
|   | Total parts                                      |                  | \$ 10,753.76    |

**LABOUR CHARGE**

|    |                                                   |                        |
|----|---------------------------------------------------|------------------------|
| 1  | To knocking out front portion & renew above parts | \$ 1,600.00 <i>800</i> |
| 2  | To putty & spray up paint works                   | \$ 1,200.00 <i>800</i> |
| 3  | To check wiring                                   | \$ 50.00 <i>30</i>     |
| 4  | To apply tuff coat                                | \$ 150.00 <i>80</i>    |
| 5  | To remove condenser & top-up aircon gas           | \$ 120.00 <i>x</i>     |
| 6  | To remove radiator & top-up coolant               | \$ 120.00 <i>x</i>     |
| 7  | To dismantle front undercarriage <i>2020</i>      | \$ 350.00 <i>x</i>     |
| 8  | To perform wheel alignment                        | \$ 150.00 <i>x</i>     |
| 9  | To replace engine mounting                        | \$ 250.00 <i>150</i>   |
| 10 | Towing Fees                                       | \$ 60.00 <i>x</i>      |
|    | Total Labour                                      | \$ 4,050.00            |
|    | <b>Grand Total</b>                                | <b>\$ 14,803.76</b>    |

GST Will be reflected in the final bills

NOTE : -

**RE : ESTIMATE FOR ACCIDENT REPAIR SLF9795G (HONDA VEZEL)**

**PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN  
THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY  
WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE  
FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.**

total: 8895.60

h/s: 7.1K.

07 Days.

**LKK Auto Consultants hence notify  
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: