

LKK Tanfph

REPAIR DETAILS**Reference****Part Source:** MRM-SG

Version: 1.0 (Last Synchronised: 15 Feb 2023)

Parts: 144

TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/SMX2596D/15/02/2023 10:42**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT DOOR RH			
2	1		*FRT DOOR OUTER HANDLE RH	0.00	0.00	bt *580.00 F
3	1		*FRT DOOR OUTER HANDLE ASSY RH	0.00	0.00	Xhm *130.00 F
4	1		*FRT DOOR LOCK	0.00	0.00	xnn *120.00 F
5	1		*FRT DOOR GLASS OUTER MOULDING RH	0.00	0.00	xnn *220.00 F
6	1		*FRT DOOR GLASS REGULATOR RH	0.00	0.00	xnn? *50.00 F
7	1		*FRT DOOR GLASS MOTOR RH	0.00	0.00	xnn *85.00 F
				0.00	0.00	nnx *270.00 F
				Sub Total (S\$)		580 1,455.00
				+ Margin on L,N Items 10.00% (S\$)		add 10% = \$638 145.50
				Total Parts (S\$)		638 1,600.50

F=Franchise part.

Sng Ah Tee Motor & Panel Service Pte Ltd/SMX2596D/15/02/2023 10:42. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No Particulars

		Lab.Type	Amount
<u>Labour Items</u>			
1	TO KNOCK RR DOOR RH,ROCKER PANEL RH,WELD ,REMOVE & REPLACE ABOVE PARTS	New	600 800.00
2	TO SPRAY RR DOOR RH ,FRT DOOR RH,ROCKER PANEL RH,PUTTY AND SPRAY PAINTING ON AFFECTEDS AREAS	New	600 850.00
3	TO CHECK WIRING	New	nn x 30.00
4	TO TRANSFER FRT DOOR GLASS RH COMPONENT	New	✓ 60.00
5	TO SETTING AND RESET	New	xnn ? 150.00
		1260	
		Gross Labour Cost (S\$)	1,890.00

Sng Ah Tee Motor & Panel Service Pte Ltd/SMX2596D/15/02/2023 10:42. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

total \$1898
Painting part
ok? Pls revert.
Sham
16/06/2023

638
1260
\$1898
5 days #


Tanfimi 92495449 (6256356)

WP' 21/2/23 e 1220

Tanfimi e 16/06/2023

5 days.

* Resing before paint



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

UEN No: 200310923R GST Reg. No: 20-0310923-R

M/S: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

BLK 3 PIONEER ROAD NORTH

#01-18

SINGAPORE 628457

PRUIS

TROY

TP-ECICS.

TAX INVOICE

NO: DLI9260844

PAGE: 1

DATE: 21/02/2023

A/C CODE: LDSAT11

TERMS: CR

VEH NO: SMX2596D

Part No	Description	Location	Qty	Unit Price	Amount
1	T67001-47150	DOOR FR RH	1	580.00	580.00
TOTAL QUANTITY:			1	TOTAL	SIN 580.00
				ADD GST @ 8%	46.40
				GRAND TOTAL	<u>SIN 626.40</u>

Print / LSK / 21/02/2023 2:06:20 pm

SALESMAN: LSK

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E. & O. E.

GOODS RECEIVED BY

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg;darren@sngahtee.com;janice@sngahtee.com

TP INSURER:
UNKNOWN

ECICS Limited (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	12/02/2023
Vehicle Reg. No.:	SMX2596D	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS, 1.8 (A)	Vehicle Reg. Date:	02/01/2021
Vehicle Colour:	BLACK		
Engine No:	2ZR2G72808	Chassis No:	ZVW516144028
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

COST OF CLAIMS

	Amount
Parts	1,600.50
Miscellaneous Items	0.00
Labour	1,890.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,490.50
+ GST 8.00% (S\$)	279.24
Nett Amount (S\$)	3,769.74

This claim is handled by: JOYCE TAN LAI CHIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System